

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22004910/EPA3Q2**Date:** 09/05/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MCV0004508_01

Claimant Vehicle No : SMJ6172R **Insured Vehicle No :** PC8470T

Date of Loss: 11/05/2022 Nature of Claim: TP Claim No: MCV2022D0002460

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ6172R**
 Make & Model: HONDA VEZEL, 1.5 HYBRID X (A) Engine No: LEB6742206
 Reg. Date: 13/03/2019 (Man. Year: 2018) Chassis No: RU31322195
 Colour: Red Odometer: 32158 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Michelin 4 mm Rear Left Side: Michelin 4 mm
 Front Right Side: Michelin 4 mm Rear Right Side: Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,492.00	1,697.28	3,794.72	69.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,832.00	1,860.00	2,972.00	61.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,324.00	3,557.28	6,766.72	65.54
+ GST 8.00/8.00% (S\$)	825.92	284.58	541.34	65.54
Nett Amount (S\$)	11,149.92	3,841.86	7,308.06	65.54
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,143.86		

INSPECTION

Date of Assignment: 24/05/2022

Date Inspected: 26/05/2022 Inspected At: Premium Automobiles Pte Ltd (HQ)
 55 UBI ROAD 1
 Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2023)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMJ6172R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LID	Dented	1,450.00 F	*912.60 FL
2	1		*REAR LID WEATHERSTRIP	Not Necessary	113.00 F	*- FL
3	1		*REAR LID CHROME TRIM	Not Necessary	425.00 F	*- FL
4	1		*HONDA EMBLEM	Not Necessary	38.00 F	*- FL
5	1		*VEZEL EMBLEM	Necessary	88.00 F	*70.00 FL
6	1		*HYBRID EMBLEM	Necessary	95.00 F	*70.00 FL
7	1		*REAR BUMPER -LOWER	Dented	1,050.00 F	*829.00 FL
8	8		*REAR BUMPER CLIP	Necessary	40.00 FS	*40.00 FS
9	1		*REAR BUMPER REFLECTOR LIGHT -LH	Not Necessary	88.00 F	*- FL
10	1		*REAR WINDSCREEN	Not Necessary	1,375.00 F	*- FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	150.00 F	*150.00 FL
12	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 F	*40.00 FL
13	1		*REAR NO PLATE	Not Necessary	80.00 F	*- FL
14	1		*SUNDRIES	Not Necessary	300.00 F	*- FL
					Sub Total (\$\$)	5,492.00 2,111.60
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 414.32
					Total Parts (\$\$)	5,492.00 1,697.28

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID	New	280.00	80.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY	New	480.00	80.00
3	TO RENEW REAR WINDSCREEN TO FACILITATE RENEWAL OF REAR LID	New	480.00	150.00
4	TO CARRY OUT WATER SEEPAGE FO REAR WINDSCREEN	New	200.00	50.00
5	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	0.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID TO REPAIR REAR END PANELLING RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	1,200.00	700.00
7	TO RESPRAY REAR BUMPER ,REAR LID AND REAR END PANELLING	New	1,600.00	700.00
8	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	100.00
Gross Labour Cost (S\$)			4,832.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >