

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 11/06/2022

User ID                      PohSuan

**Section A - Accident Details**

Registration Number	SHD6313S
Case Reference Number	TAX/05/22/2065
Registration Date	1/11/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NG WOON KWANG
Type of Accident	Head to Rear
Accident Date and Time	23/5/2022 8:20 PM
Accident Reported Date and Time	24/5/2022 9:55 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24115064
Special Instruction to ARC, if any	REAR PORTION
Prepared Date and Time	24/5/2022 10:39 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$918.00	\$300.00
Total Spare Part Cost	\$4,433.80	\$1,036.66
Total Other Cost	\$500.00	(\$286.66)
<b>TOTAL COST</b>	<b>\$6,527.80</b>	<b>\$1,250.00 (L/S)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>RASUL (LKK) / NTUC</b>
ARC / Surveyor Sign Off Date	<b>26/05/2022 4:03 PM</b>	<b>26/05/2022 1:44 PM</b>
Signature		
Remarks	Total number of repair days = 2 days. SUP = 0 day.	LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO .

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/06/2022

User ID                      PohSuan

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2206-0118	<b>Invoice Number</b>	
<b>Quotation Date</b>	10.06.2022	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

<b>Job Scope</b>	<b>Quotation from AR</b>	<b>Adjusted by Surveyor, if applicable</b>
TO REPAIR REAR PORTION	\$676.00	\$200.00
<b>Total Labour</b>	<b>\$676.00</b>	<b>\$200.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$100.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$918.00</b>	<b>\$300.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$326.66)
<b>Total Other Costs</b>	<b>\$500.00</b>	<b>(\$286.66)</b>

**Part 4 - Spare Parts / Material Usage**

<b>Part Number</b>	<b>Portion</b>	<b>Stock Number</b>	<b>Part Name</b>	<b>Quantity</b>	<b>List Price (\$)</b>	<b>Discount (%)</b>	<b>Final Price (\$)</b>	<b>Estimator Approved</b>	<b>Surveyor Approved</b>
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check
		5246247030	PAD, RR BUMPER, RH & LH , 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		5246247020	PAD, RR BUMPER, RH & LH , 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		5246247010	PAD, RR BUMPER, RH & LH , 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace
		5219147030	SEAL, RR BUMPER ARM, RH & LH	2.00	\$11.00	25.00	\$16.50	Replace	Replace
		5259968030	STOPPER, RR BUMPER, RH & LH	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given
		5259147050	SEAL, RR BUMPER , RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given
		5259247040	SEAL, RR BUMPER , LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		5245347010	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace

✓  
X  
✓  
✓  
✓  
✓  
✓  
✓  
X  
X  
X  
X  
X  
✓  
✓

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/06/2022

User ID                      PohSuan

		52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given	X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Check	X
		89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
		90189060 29	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given	X
		81551472 81	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
		81561471 51	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
		81581470 10	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
		81591470 10	LENS & BODY ASSY , RR BUMPER , LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
		58398470 50	COVER, REAR FLOOR UNDER , RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
		58399470 30	COVER, REAR FLOOR UNDER , LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
		66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
		58307470 90	END PANEL SUB-ASSY, BODY LOWER BACK	0.00	\$629.80	0.00	\$0.00	Replace	Not Given	X
<b>Total</b>					<b>\$5,089.30</b>		<b>\$786.46</b>			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace
		52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace
<b>Total</b>					<b>333.60</b>		<b>250.20</b>		

	1,036.66	
+	200.00	
+	340.00	L/S \$1,250/-
	1,576.66	
	-20%	
	1,261.33	