

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 61846**
Date Estimated : **18/05/2022**
Prepared By : **Yap Mee Key**

- ESTIMATE REPAIR FOR -
Koh Shin How (Xu Xinhao)
Blk 60 Flora Drive
#02-37

Singapore 508858

- ACCOUNT - 45912
EQ Insurance Company Limited
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SW54Z	WBA5R12000AK721	30/04/2019	330i LIM	16710

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper.	850.00	0.00	850.00
To respray rear bumper.	986.00	0.00	986.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00	0.00	168.00
To check electrical wiring system.	168.00	0.00	168.00
Sundries.	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (BASIS PDC	1,281.15	1.00	0.00	1,281.15

SUPPLEMENTARY ITEMS

Total Labour :	2,252.00
Total Parts :	1,281.15
Total Labour & Parts :	3,533.15
Deduction for Excess :	
Total Repair Costs less Excess:	3,533.15
GST @7%:	247.32
Grand Total :	3,780.47