

Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 1 of 5

Estimate No. : b1 61846
Date Estimated : 18/05/2022
Prepared By : Yap Mee Key

- ESTIMATE REPAIR FOR -
Koh Shin How (Xu Xinhao)
Blk 60 Flora Drive
#02-37

Singapore 508858

- ACCOUNT - 45912
EQ Insurance Company Limited
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SW54Z	WBA5R12000AK72151	30/04/2019	330i LIM	16710

DESCRIPTION

To replace rear bumper.

To respray rear bumper and affected areas.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

To check electrical wiring system.

Sundries.

850 / 1,275.00
986 934 / 1,038.00
168 / 177.00
168 / 177.00
80.00

Total Labour 1: 2,747.00

DESCRIPTION	QTY	PRIC	VALUE
EXPANDING NUT	2	0.65	1.30
PLASTIC INSERT BOLT	2	1.60	3.20
FILLISTER HEAD SCREW (ISA)	2	3.15	6.30
RR BUMPER CARRIER	1	446.75	446.75
RR BUMPER CTR GUIDE	1	138.15	138.15
PDC HOLDER INSIDE LH	1	10.15	10.15
PDC HOLDER OUTSIDE LH	1	11.65	11.65
PDC HOLDER OUTSIDE RH	1	11.65	11.65
RR BUMPER CTR BOTTOM GUIDE	1	65.80	65.80
RR BUMPER (PDC)	1	1,176.40	1,176.40
RR BUMPER TOW HOOK COVER	1	39.35	39.35
RR BUMPER BREATHER COVERING	2	56.80	113.60
Exh.extnsion	1	24.25	24.25
Total Parts :			2,048.55



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 2 of 5

Estimate No. : b1 61846
Date Estimated : 18/05/2022
Prepared By : Yap Mee Key

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SW54Z	WBA5R12000AK72151	30/04/2019	330i LIM	16710

Steve (LKK)

25/5/22, 11.00

WZ MC

3 djs

P/P

W B L H

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	2,747.00
Parts	:	2,048.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	335.69
Grand Total	:	5,131.24

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY ****

**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****