

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III22004915/KNY3E2**Date:** 27/03/2023**REFERENCE**

Insured/Claimant: COMFORTDELGRO RENT-A-CAR PTE LTD

Policy No: 104283

Date of Loss: 10/05/2022

Nature of Claim: OD Claim No: MFL2022D0002473

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNC6973X**

Make & Model: HYUNDAI SANTA FE, 2.4 (A)

Engine No: G4FTMU401439

Reg. Date: 09/11/2021 (Man. Year: 2021)

Chassis No: KMHS3811MMU018561

Colour: Metallic Pearl White

Odometer: 13101 km

Engine Capacity: 1598 cc

Market Value/New Car Price: S\$190,000.00

Price:

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19

Rear Tyre Size: 235/55 R19

Front Left Side: Continental 9 mm

Rear Left Side: Continental 9 mm

Front Right Side: Continental 9 mm

Rear Right Side: Continental 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,645.84	3,813.84	832.00	17.91
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	850.00	340.00	510.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,506.84	4,164.84	1,342.00	24.37
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	5,506.84	3,414.84	2,092.00	37.99
+ GST 7.00/8.00% (S\$)	385.48	273.19	112.29	29.13
Nett Amount (S\$)	5,892.32	3,688.03	2,204.29	37.41

INSPECTION

Date of Assignment: 25/05/2022 Present Location: ComfortDelGro Engineering Pte Ltd (Braddell)

Date Inspected: 25/05/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Braddell)

205 Braddell Road
Singapore 579701

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Mar 2023)
Parts:	M1-SUV	HYUNDAI SANTA FE 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNC6973X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH RIM 19	Dented	1,573.50 F (20/0.00)%	*1,573.50 FL
2	1		*REAR LH TYRE	Serviceable	300.00 FS	*- FS
3	1		*FRONT LH TYRE	Serviceable	300.00 FS	*- FS
4	1		*FRONT LH RIM	Dented	1,573.50 F (20/0.00)%	*1,573.50 FL
5	1		*FRONT LH WHEEL HUB	Bent	452.20 F (20/0.00)%	*452.20 FL
6	1		*FRONT LH KUNCKLE ARM	Bent	609.90 F (20/0.00)%	*609.90 FL
7	1		*FRONT LH LOWER ARM	Bent	502.20 F (20/0.00)%	*502.20 FL
8	1		*LH POWER STEERING TIE ROD END	Serviceable	76.00 F (20/0.00)%	*- FL
9	1		*LH POWER STEERING TIE ROD	Serviceable	200.00 F (20/0.00)%	*- FL
Supplementary #1						
10	1		*BRAKE VALVE 2 PCS	Necessary	56.00 F	*56.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. (x/y)%=(PDisc/Depr)%.

Sub Total (\$\$)	5,643.30	4,767.30
- List Item Discount on L Items 0.00/20.00% (\$\$)	997.46	953.46
Total Parts (\$\$)	4,645.84	3,813.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE RH FRONT SUPPENSION UNIT TO ASSIST REPAIR AND REPLACE (LOWER ARM ,KUNCKLE ARM ,HUB,STEERING TIE ROD ,RIM)	New	500.00	200.00
2	TO PERFORM 4 WHEEL ALIGNMENT ADJUSTMENT	New	120.00	80.00
3	TO REMOVE AND REPLACE LH REAR RIM ,TYRE AND BALANCING	New	150.00	60.00
<u>Supplementary #1</u>				
<u>Labour Items</u>				
4	WHEEL ALIGNMENT	New	80.00	0.00
Gross Labour Cost (\$\$)			850.00	340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >