

Vehicle Damage Assessment Report for [SNC6973X]

Estimate Created: 26/05/2022 02:42 by LKK_assignments
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 22/03/2023 07:06 by LKK_assignments (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company	india international	Claim Number	MFL2022D0002473
Claim Type	OD		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

Vehicle Information

Brand	Hyundai	Model	Starex
Engine Type			
License Plate Number	SNC6973X	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$4,164.84 WITH 2 WORKING DAYS

Insurlogic 5 (22/03/2023 07:05)

- Pre Review done base on survey information provided
Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Pre Review by: Insurlogic
Parts: \$3,147.00 - 20% = \$2,517.60
Check item (including SN) : \$2,072.24
Check Labour : \$500.00
Labour: \$140.00
Paint: N.A
OD fee: \$11.00
Total: \$5,240.84
Repair Days: 2 Working days

Insurlogic 4 (26/05/2022 03:58)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR LH RIM 19'		1	1573.50	-20.00 %	1,258.80
FRONT LH RIM 19'		1	1573.50	-20.00 %	1,258.80
FRONT LH WHEEL HUB		1	452.20	-20.00 %	361.76
FRONT LH KNUCKLE ARM		1	609.90	-20.00 %	487.92
FRONT LH LOWER ARM		1	502.20	-20.00 %	401.76
BRAKE VALVE		1	56.00	-20.00 %	44.80

Parts Subtotal 3,813.84

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
MERIMEN FEE		1.0	11.00	0.00 %	11.00

Materials Subtotal 11.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
TO REMOVE RH FRONT SUSPENSION UNIT TO ASSIST REPAIR AND REPLACE	RnR	200.00	0.00 %	200.00
WHEEL ALIGNMENT	RnR	80.00	0.00 %	80.00
TO REMOVE & REPLACE LH REAR RIM, TYRE & BALANCING	RnR	60.00	0.00 %	60.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 340.00

Paint Labor Subtotal 0.00

Labor Subtotal 340.00

Summary

Repair Cost 4,164.84

Discount(0 %) (0.00)

4,164.84

Excess (0.00)

GST(0.00 %) 0.00

Grand Subtotal	4,164.84
----------------	----------