

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: India International Insurance Pte Ltd
64 Cecil Street
#04-00 IOB Building
Singapore 049711

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sundari Nagarajan

Date: 16 Mar 2023

Preliminary Advice

Vehicle No	: SNC6973X	Accident Date	: 10/05/2022
Make	: HYUNDAI SANTA FE	Policy No.	: 104283
Assignment Date	: 25/05/2022	Excess	: S\$750.00
Date of Inspection	: 25/05/2022	Est. Duration of Repair	: 2
Inspection At	: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL) 205 BRADDELL ROAD SINGAPORE 579701		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,506.84 (inclusive supp \$136.00)
Revised Amount	:S\$	4,244.84
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,244.84
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	190,000.00
COE / PARF Rebate	:S\$	97,905.00
Salvage Value	:S\$	
Margin for Repair	:S\$	92,095.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :