Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance

(Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Irene Tay Hui Ping Date: 31 May 2022

Preliminary Advice

Insured

: SBU64G

Vehicle No

TP Vehicle

: SLX2907C

Accident Date

: 19/05/2022

No

Assignment Date: 25/05/2022

Make Date of : MERCEDES-BENZ E220

Est. Duration of

Inspection

: 30/05/2022

Repair

: 2

Inspection At: AH LIM MOTOR COMPANY (AMK)

10 ANG MO KIO INDUSTRIAL PARK 2A, #01-09 AMK

AUTOPOINT

SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 5,961.10 Revised Amount :S\$ 2,285.00 Check Items (Estimated) :S\$ 1,467.00 :S\$ 3,752.00 Total

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$
Salvage Value :S\$
Margin for Repair :S\$

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed
	excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.