

Vehicle Damage Assessment Report for [SKS8950A]

Estimate Created: 25/05/2022 07:26 by LKK_admin-a
(LKK_Auto_Consultants_Pte_Ltd)

Owned: 03/03/2023 14:33 by LKK_cs-a (LKK_Auto_Consultants_Pte_Ltd)

General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Volkswagen	Model	Jetta
Engine Type			
License Plate Number	SKS8950A	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:
CONCLUDED THE COST OF REPAIR AT \$4,100.00 WITH 4 WORKING
DAYS

Insurlogic 5 (03/03/2023 14:33)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
BOOTLID TSI EMBLEM		1	62.00	-5.00 %	58.90
BOOTLID JETTA EMBLEM		1	75.00	-5.00 %	71.25
BOOTLID WEATHERSTRIP		1	293.00	-5.00 %	278.35
REAR BUMPER		1	1366.35	-5.00 %	1,298.03
REAR BUMPER BEAM		1	606.00	-5.00 %	575.70
REAR BUMPER SPONGE		1	95.00	-5.00 %	90.25
REAR BUMPER SIDE RETAINERS		1	190.00	-5.00 %	180.50
REAR BUMPER REFLECTORS		1	75.00	-5.00 %	71.25
REAR BUMPER INNER TOP RETAINER		1	151.00	-5.00 %	143.45
SET REAR BUMPER CLIPS		1	50.00	-5.00 %	47.50
REAR BUMPER LOWER GARNISH		1	210.00	-5.00 %	199.50
REAR FLOOR PANEL TOOLS SPONGE		1	442.00	-5.00 %	419.90

Parts Subtotal 3,434.58

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
REAR BUMPER PDC SENSORS		1.0	200.00	0.00 %	200.00

Materials Subtotal 200.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
TO CHECK WIRING	RnR	20.00	0.00 %	20.00
TO DISMANTLE & REPLACE REAR REVERSE SENSOR	RnR	50.00	0.00 %	50.00
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	RnR	80.00	0.00 %	80.00
TO RESET & DIAGNOSIS REPROGRAMME SYSTEM	RnR	50.00	0.00 %	50.00
TO SPRAY RUST PROOFING	RnR	30.00	0.00 %	30.00

LABOUR FOR PANEL BEATING & REPLACED PARTS	RnR	680.00	0.00 %	680.00
---	-----	--------	--------	--------

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
TO PUTTY & SPRAY PAINTING	Full spray	600.00	0.00 %	600.00
Labor Rate	S\$ 50 / Hour		General Labor Subtotal	910.00
			Paint Labor Subtotal	600.00
			Labor Subtotal	1,510.00

Summary

Repair Cost	5,144.58
Discount(20 %)	(1,028.92)
	4,115.66
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	4,115.66