



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22003268/Rqy3e2-1	
			Date: 01/06/2022	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 9366E	Veh. Inspected	SJD 7667R	
Policy No.		Coverage (\$)	0.00	
Claim No.	21/22/22/VC00/025627	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	08/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC 1.5 TURBO SR	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MRHFC1660GT000038	Colour	BLUE	
Odometer	132400 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40Z R18	PIRELLI	6 mm	
L/H Front Tyre	235/40Z R18	PIRELLI	6 mm	
R/H Rear Tyre	235/40Z R18	PIRELLI	6 mm	
L/H Rear Tyre	235/40Z R18	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/04/2022	Inspection Date	08/04/2022	
Survey held at	1007 BUKIT MERAH #01-09			
Repairer	ZOLAR AUTO SERVICES			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	