

Zolar Auto Services

No 8 Kaki Bukit Ave 4 Premier (Gate 2)

06-43 S415875

Contact No. : 9185 4218

E-Mail : zolar.auto@gmail.com

Date : 8-Apr-22

Registration no. : SJD7667R / Honda Civic 1.5 Turbo VTIS SR / 2016

DOA : 4-Apr-22

Estmate No. : ZAS034_SJD7667R_CIVIC

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

1	1	Bonnet <i>bt</i>	879.20
2	2	Bonnet hinges @ \$ 145.00 <i>Xnn</i>	290.00 <i>X</i>
3	1	Bonnet inner lock <i>Xnn</i>	205.40 <i>X</i>
4	1	Bonnet insulator <i>Xnn</i>	196.30 <i>X</i>
5	1	Front bumper <i>Xnn</i>	979.20 <i>X</i>
6	2	Front bumper side retainer @ \$ 147.40 <i>Xnn</i>	294.80 <i>X</i>
7	1	Front fender RH <i>bm</i>	631.50
8	1	Front fender side marker lamp RH <i>Xnn</i>	224.60 <i>X</i>
9	1	Front fender inner shield RH <i>de</i>	177.90
10	1	Front fender inner panel RH <i>repair</i>	312.00 <i>X</i>
11	1	Washer tank <i>de</i>	223.00
12	1	Wing mirror RH <i>dis</i>	856.00
13	1	Wing mirror cover RH <i>sw</i>	105.00
14	1	Front door RH <i>bt</i>	1380.30
15	1	Front door weatherstrip RH <i>ne</i>	186.11
16	1	Front door inner trim RH <i>Xnn</i>	472.00 <i>X</i>
17	1	Front door inner lock RH <i>Xnn</i>	361.40 <i>X</i>
18	1	Front door checker RH <i>Xnn</i>	88.60 <i>X</i>
19	2	Front door hinges RH @ \$ 92.70 <i>Xnn</i>	185.40 <i>X</i>
20	1set	Front door black tape RH <i>ne</i>	118.00
21	1	Front door glass regulator assy RH <i>Xnn</i>	482.00 <i>X</i>
22	1	Front knuckle arm RH <i>Xnn</i>	424.65 <i>X</i>
23	1	Front knuckle arm bearing RH <i>Xnn</i>	284.20 <i>X</i>
24	1	Front lower arm RH <i>Xnn</i>	380.10 <i>X</i>
25	1	Front anti-roll bar <i>Xnn</i>	275.80 <i>X</i>
26	1	Front stabilizer link RH <i>Xnn</i>	105.20 <i>X</i>
27	1	Front shock absorber RH <i>Xnn</i>	410.00 <i>X</i>
			10528.66

Less 20%

2105.73

8422.93

4557.01
20%
3645.60

Zolar Auto Services

No 8 Kaki Bukit Ave 4 Premier (Gate 2)

06-43 S415875

Contact. No. : 9185 4218

E-Mail : zolar.auto@gmail.com

Date : 8-Apr-22

Registration no. : SJD7667R / Honda Civic 1.5 Turbo VTIS SR / 2016

DOA : 4-Apr-22

Estimate No. : ZAS034_SJD7667R_CIVIC

S/N	Qty	Item	Amount
-----	-----	------	--------

SPECIAL NETT ITEMS

1	1	Sundries	80.00	20
2	1set	Bonnet insulator clips	40.00	X
3	1	Front bumper grille	280.00	X
4	1set	Front bumper clips	80.00	30
5	1	Front fender sealant RH	70.00	30
6	1	Front fender inner panel sealant RH	65.00	40
7	1set	Front fender inner shield clips RH	150.00	30
8	1	Front door inner seal RH	30.00	/
9	1set	Front door inner trim clips RH	35.00	/
10	1	Front tyre RH	480.00	X
11	1	Front rim RH	750.00	350
			2060.00	
PART TOTAL			10482.93	

LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on accident area.	1400.00	600
2	1	Check wiring system after disconnect and connect.	80.00	X
3	1	To R&R RH front door component, check and alignment.	150.00	60
4	1	To R&R RH front undercarriage for replacement parts.	320.00	X
5	1	To R&R RH front tyre and balancing.	60.00	40
6	1	To conduct wheel alignment.	100.00	60
7	1	To apply undercoating for rust roofing.	200.00	60
8	1	Spray painting on accident area.	1250.00	600
LABOUR TOTAL			3560.00	

Total Parts and Labour Cost of Repair

14042.93

Pre-Repair Survey :-

Name :

RASUL

Contact no. :

90010068

Date / Time : 08/04/2022 @ 1600hrs

5 days / Lumpsum

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: