

J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,
Defu Industrial Park C, Singapore 539186
Tel : 6343-0934 Fax : 6343-0921
Email : jmartauto@gmail.com
Registration No: 201400246D
GST Reg. No: 201400246D

23-May-22

Our ref : TP/5120/22

Automobile Tyre Pte Ltd

TP China
Asker.

RE : estimate cost for vehicle no : SLC 6622H

1 pc	rear bumper top	zmbd	\$	1,110.00	✓
1 pc	rear bumper centre	behnd		780.00	✓
1 pc	rear bumper lower	at		460.00	✓
1 pc	rear bumper rh reflector	zmbd		78.00	✓
1 pc	rear bumper rh signal light	new		36.00	✓
2 pcs	rear bumper reverse sensor	1 piece dmd		472.00	236
1 pc	rear bumper rh retainer	new		110.00	✓
				3,046.00	
				304.60	
				2,741.40	
				500.00	300
				500.00	350
				30.00	✓
				3,771.40	
				264.00	
				4,035.40	

2664 less 10%
2387.60

680

Plus 7% GST

SD : Four thousand thirty-five & cents forty only.

Adrian L
2/8 23/05/22

02 days

total: 3077.60
1/5: 2410

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: