

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 61912**
Date Estimated : **24/05/2022**
Prepared By : **Jack Ng Guo Ming**

Page No. : **1 of 5**

- ESTIMATE REPAIR FOR -

Poon Yin Yin
Blk 49 Hillview Avenue
#04-04

Singapore 669615

- ACCOUNT - 136

Ergo Insurance Pte Ltd
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMS9399L	WBA5F32050FH55452	20/01/2020	320i Sedan	34115

DESCRIPTION	VALUE
To replace front bumper, right front fender and all damage attachment.	5,100.00
To respray front bumper, right front fender.	1,923.00
To tow accident vehicle to PML workshop.	150.00
To carry out body cavity preservation. (Per panel).	118.00
To replace electromechanical power steering including program, initialize steering column adjustment and conduct check for proper function.	885.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	531.00
To remove and install front suspension to facilitate the jacking of chassis and mounting of car on celette bench.	1,062.00
To remove and install brake discs, brake pads and brake calipers including brake test and conduct check for leak.	1,003.00
To replace tyre and wheel rim including balancing. (1x).	94.00
To remove and install front suspension for inspection and replace damaged parts.	2,655.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	177.00
To replace right headlight.	481.00
To check electrical wiring system at the front section	177.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 61912**
Date Estimated : **24/05/2022**
Prepared By : **Jack Ng Guo Ming**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMS9399L	WBA5F32050FH55452	20/01/2020	320i Sedan	34115

DESCRIPTION	VALUE
for proper function including adjustment of headlights.	
Sundries.	300.00

Total Labour 1: **14,656.00**

DESCRIPTION	QTY	PRIC	VALUE
FRT AXLE SUPPORT RWD	1	1,404.00	1,404.00
RH TENSION STRUT WITH HYDR. MOUNT	1	286.15	286.15
RH WISHBONE BOTTOM W/RUBBER MOUNTIN	1	343.35	343.35
RH SWIVEL BEARING CAMBER CORRECTION	1	548.95	548.95
FRT RH CARRIER	1	499.05	499.05
FRT STABILIZER WITH RUBBER MOUNTING	1	411.70	411.70
FRT SUPPORT BEARING	1	234.95	234.95
FRT RH SWING SUPPORT	1	105.15	105.15
FRT RH SPRING STRUT	1	537.95	537.95
ADDITIONAL DAMPER FRT	1	45.35	45.35
SPRING PAD LOWER	1	14.05	14.05
FRT BRAKE DISC VENTILATED 307X24	1	256.85	256.85
ALLOY RIM 7.5X18 DOUBLE SPK 782	1	1,069.35	1,069.35
FRT RH SIDE PANEL BRACKET 1	1	60.60	60.60
FRT RH SIDE PANEL	1	815.60	815.60
LH RETAINING FRAME	1	83.85	83.85
RH RETAINING FRAME	1	83.85	83.85
FRT BUMPER PANEL PRIMED (LINE PDC/P	1	1,089.85	1,089.85
RH HEADLIGHT LED AHL	1	3,397.70	3,397.70

Total Parts : **11,288.30**



Labour 1	:	14,656.00
Parts	:	11,288.30
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,816.10
Grand Total	:	27,760.40

**** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY****

**** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE ****