Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Adeline Chng Pei Wen Date: 03 Feb 2023

Preliminary Advice

Insured Vehicle No : GBF5321K

TP Vehicle No : SLC6926G Accident Date : 24/05/2022 Make : TOYOTA COROLLA ALTIS Assignment Date : 25/05/2022

Date of Inspection : 26/05/2022 Est. Duration of Repair : 9

Inspection At : TEAM AUTO PRO PTE LTD - SIN MING (HQ)

160 SIN MING DRIVE #01-14 SIN MING AUTOCITY

SINGAPORE 575722

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 21,893.38 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 10,279.83 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 10,279.83 |
| | | |
| Lump Sum Repair | :S\$ | 8,200.00 |

Total Loss Consideration

| New for Old Value | :S\$ |
|--------------------|------|
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

| (|) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly |
|---|---|---|
| | | let us have your authorisation. |

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.