

Certification for Bus Repairs

SBS Transit

CBR REF NO. : BB20222431

Depot : BB

Report No.: AR-2022-0306

BUS VEHICLE NO. : SBS6194K

Driver's Co no. & Name : 21930 Lim Tong Heng

Accident Date : 20/05/2022

Date in : 20/05/2022

Date Out : 28/05/2022

Yr Of Reg	Make / Model	Chassis No.
2012	MB Citaro O530, SD, AC, 2 Axle	WEB62808323123176

Stock Code	Description	Quantity	Total Material cost(S\$)	
30600047	FASTENER;OS/NS;FRT BUMPERETTE	1	\$11.00	✓ NEC
30600050	BRACKET N/S;FRT BUMPERETTE	1	\$268.00	✓ BT
30117511	FRONT WINDSCREEN.COMPOUND SAFETY.G	1	\$832.00	✓ CRA
30600181	COVER;OUTSIDE ATTACHMENT PARTS	1	\$191.00	✓ BR
30600386	BUMPERETTE;FRT BUMPERETTE.N/S	1	\$590.00	✓ BR
30117520	GLASS.QUARTER.FRT N/S	1	\$359.00	✓ BR
30600025	BLINKER LAMP;FRT LEFT	1	\$44.00	✓ BR
99001048	SILKAFLEX 255 EXTRA BLACK	10	\$98.00	✓ NEC
99002069	PAINT C6000 MERCEDES PURPLE	1	\$21.12	✓ NEC
99002070	PAINT C6000 MERCEDES WHITE	1	\$20.76	✓ NEC
TOTAL FOR PARTS			S\$ 2434.88	
S/N	Labour / Spray Painting / Contractor Cost	Amount		
1	(3) Workshop Labour for Repair and Replace Bus Damage & Parts	S\$	1128.00	✓
2	Contractor's repair charges	S\$	-	
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			S\$ 1128.00	
Repair cost of Advertisement / Livery			S\$ -	
TOTAL DAMAGE			S\$ 3562.88	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9- 10800