

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

JTFAT 3575201545

TP Somp

Venn.

ESTIMATE OF REPAIR

Veh# : GBC1568H

Model: TOYOTA DYNA

Accident Date : 24/5/2022

236/2011

Location : 29 UBI ROAD 4 DICKSON AUTO CENTRE

3P: SLM5201T (SOMPO)

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Distorted</i>	1,320.00	645	
2	1 pc	Front bumper n/s bracket <i>New</i>	120.60	X	
3	1 pc	Front panel "DYNA" emblem <i>New</i>	125.60	X	
4	1 pc	Front n/s corner panel <i>Dented</i>	210.00	✓	
5	1 pc	Front grille <i>Free</i>	640.40	X	
6	12 pcs	Front grille clips		48.00	X
7	1 pc	Front n/s head-lamp <i>ambled</i>	720.20	✓	
8	2 pcs	Front n/s head-lamp clips <i>New</i>		12.00	X
9	1 pc	Front regn no. plate <i>New</i>		35.00	X
10	1 pc	Front n/s door company sticker <i>New</i>		30.00	✓
11	1 pc	Front n/s safety first sticker <i>New</i>		50.00	20
		<i>Slip burnish</i> 245 ✓	Sub-Total:	3,136.80	175.00
		<i>cut</i>	25%	0%	0%
		<i>1820.20</i> <i>SN: 50</i>	After Less %:	2,352.60	175.00
		<i>1365.15</i>			
		Labour			
1		To remove and replace front damage parts		1,000.00	400
2		To spray painting.		800.00	500
3		To check wiring.		80.00	30
4		To re-seal anti-rust.		80.00	40
		Sub-Total:		1,960.00	
		Total:		4,487.60	
		After Less 20%:		3,590.08	

lulan

Chan San

Director

DipEng, AAF, BMM, MSAE Aust



KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8778 1999
24 hr accident call

Mobil 1



PAYNOW

Adrian Lj
L/S. 28/05/22.

04 Days.

total. 2385.15

L/S: 1.91K