Plate
Number
SDU9191P

Case Number
MPC2022D0002715

Brand
BMW
Brand
Bran

Technician SA Parts Manager

- LKK_assignments -

No data

Pre Review done base on survey information provided Take note that this review is done before finalization, a final review on repair cost to be concluded after repair.

Pre Review By : Insurlogic Amount : \$9644.95 Check: \$156.84

Repair Duration: 6 working days