

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg

INSURER:

India International Insurance Pte Ltd (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (Own Damage)	Ref. No:	
Policy No:	D18MPC0000192-03	Date of Loss:	22/05/2022
Vehicle Reg. No.:	SDU9191P	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHIA TECK LEONG JIMMY		
Make/Model:	BMW 730LI, 2.0 LED NAV HUD SR (A)	Vehicle Reg. Date:	03/07/2017
Vehicle Colour:	Silver		
Engine No:	26189659B48B20B	Chassis No:	WBA7A2020GL97062
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7 6day,		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		

*Not Authorised**Running Repair**Ex 77***COST OF CLAIMS**

	Amount
Parts	11,483.74
Miscellaneous Items	11.00
Labour	3,350.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	14,844.74
+ GST 7.00% (S\$)	1,039.13
Nett Amount (S\$)	15,883.87

This claim is handled by: **PATRICK TIA JEE KIANG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 May 2022)
 Parts: 143 BMW 730LI 2.0 LED NAV HUD SR (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SDU9191P/25/05/2022 14:51
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	5	0.00	R *1,974.75 F	X
2	1		*FRONT LH FENDER	5	0.00	R *1,304.95 F	✓
3	1		*FRONT LH FENDER EMBLEM M	5	0.00	R *83.80 F	✓
4	1		*FRONT LH FENDER PROTECTOR	5	0.00	R *198.70 F	X
5	1		*FRONT LH DOOR	5	0.00	R *2,352.35 F	✓
6	1		*FRONT LH DOOR GARNISH	5	0.00	R *238.55 F	✓
7	1		*FRONT LH DOOR WEATHER STRIP	5	0.00	R *243.65 F	✓
8	1		*REAR LH DOOR	5	0.00	R *2,585.35 F	✓
9	1		*REAR LH DOOR GARNISH	5	0.00	R *238.55 F	✓
10	1		*REAR LH DOOR WEATHER STRIP	5	0.00	R *243.65 F	✓
11	1		*REAR BUMPER	5	0.00	R *2,365.45 F	X
12	1		*REVERSE SENSOR OUTER	5	0.00	R *251.20 F	✓
13	1		*REVERSE SENSOR COVER	5	0.00	*7.20 F	7

F=Franchise part.

Sub Total (S\$) 12,088.15
 - List Item Discount on L Items (S\$) 604.41
 Total Parts (S\$) 11,483.74

ComfortDelGro Engineering Pte Ltd/SDU9191P/25/05/2022 14:51. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey.
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

Qty Particulars

Miscellaneous Items

Amount

1 OD/TP Case (Insurer)

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO PANEL BEAT ON LH FRONT BUMPER TO REAR BUMPER ,LH CENTRE PILLAR LH FENDER ,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	1,000.00	750
2	TO PUTTY,RESPRAY ON LH FRT BUMPER ,LH FENDER ,LH FRT DOOR,LH REAR DOOR,LH REAR FENDER AND REAR BUMPER	New	1,700.00	1300
3	TRANSFER DOOR PARTS TO NEW 2 DOORS	New	300.00	300
4	CHECK LIGHTING AND WIRING	New	50.00	30
5	TO RESET ECU SYSTEM	New	300.00	?

Gross Labour Cost (S\$)

3,350.00

ComfortDelGro Engineering Pte Ltd/SDU9191P/25/05/2022 14:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >