

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO PANEL BEAT ON LH FRONT BUMPER TO REAR BUMPER ,LH CENTRE PILLAR LH FENDER ,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	1,000.00
2	TO PUTTY,RESPRAY ON LH FRT BUMPER ,LH FENDER ,LH FRT DOOR,LH REAR DOOR,LH REAR FENDER AND REAR BUMPER	New	1,700.00
3	TRANSFER DOOR PARTS TO NEW 2 DOORS	New	300.00
4	CHECK LIGHTING AND WIRING	New	50.00
5	TO RESET ECU SYSTEM	New	300.00
Gross Labour Cost (S\$)			3,350.00

ComfortDelGro Engineering Pte Ltd/SDU9191P/25/05/2022 14:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

TO: Kenneth

Parts : 7540.05

+ Supp = 183.00

= 7725.05

- 5% = 386.25

= 7338.80

2480.00

+ Labor

= 9818.80

24/6/22 - Kneig

2480

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 25 May 2022)

Parts: 143 **BMW 730LI 2.0 LED NAV HUD SR (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SDU9191P/25/05/2022 14:51

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	5	0.00	R *1,974.75 F	X
2	1		*FRONT LH FENDER	5	0.00	Ry *1,304.95 F	✓
3	1		*FRONT LH FENDER EMBLEM M	5	0.00	Mr *83.80 F	✓
4	1		*FRONT LH FENDER PROTECTOR	5	0.00	Sn *198.70 F	X
5	1		*FRONT LH DOOR	5	0.00	Ry *2,352.35 F	✓
6	1		*FRONT LH DOOR GARNISH	5	0.00	Mr *238.55 F	✓
7	1		*FRONT LH DOOR WEATHER STRIP	5	0.00	Mr *243.65 F	✓
8	1		*REAR LH DOOR	5	0.00	By *2,585.35 F	✓
9	1		*REAR LH DOOR GARNISH	5	0.00	Mr *238.55 F	✓
10	1		*REAR LH DOOR WEATHER STRIP	5	0.00	Mr *243.65 F	✓
11	1		*REAR BUMPER	5	0.00	R *2,365.45 F	X
12	1		*REVERSE SENSOR OUTER	5	0.00	Sen *251.20 F	✓
13	1		*REVERSE SENSOR COVER	5	0.00	*7.20 F	7

F=Franchise part.

Sub Total (\$\$)	12,088.15
- List Item Discount on L Items (\$\$)	604.41
Total Parts (\$\$)	11,483.74

ComfortDelGro Engineering Pte Ltd/SDU9191P/25/05/2022 14:51. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

7142.05

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 24 Jun 2022)**Parts:** 143 BMW 730LI 2.0 LED NAV HUD SR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SDU9191P/24/06/2022 14:16**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*DOOR RUBBER/LH FRT DR	5	0	*91.50 F
2	1		*DOOR RUBBER(LH REAR DR	5	0.00	*91.50 F
Sub Total (\$\$)						183.00
- List Item Discount on L Items (\$\$)						9.15
Total Parts (\$\$)						173.85

F=Franchise part.

ComfortDelGro Engineering Pte Ltd/SDU9191P/24/06/2022 14:16. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**