

# E M Solution Pte Ltd

160 Sin Ming Drive #03-18/19, Sin Ming Autocity  
 Singapore 575722  
 Tel: 64560226 Fax: 64584500  
 GST Reg. No: 201016308K

*Not Authorized  
 11 May @ 2.05pm  
 Presing After Paint  
 3 days*

M/s **Teo Car Rental**  
 Blk 621 Bukit Batok Central #10-510  
 Singapore 650621

## ESTIMATE

Date : 26th May 2022

Veh No : **SLT 7000G**  
 Make/Model : **Renault Kadjar**  
 Chassis No : VF1RFE00355897309  
 Date of Acc : 03.04.22  
 TP Veh No : SHC 8151J

S/No	Qty	Description	Unit Price	Amount
<b>Materials</b>				
1	1 pc	Frnt Bumper <i>1395</i>	<i>material/Dis</i> \$	1,793.50 ✓
2	1 pc	Fr Fender Arch Garnish RH <i>600</i>	<i>Red</i> \$	1,012.80 ✓
				\$ 2,806.30
				Less 10% : \$ 280.63
				\$ 2,525.67
<b>Special Nett</b>				
3	1 set	Frnt Bumper Clips	\$ <i>Ma</i>	55.00 ✓
4	1 set	Frnt Fender Arch Garnish Clips	\$ <i>Ma</i>	35.00 ✓
5	1 pc	Frnt Sport Rim RH	\$ <i>Pa</i>	650.00 X
				Parts Total : \$ 3,265.67
<b>Labour</b>				
1	To remove & rearrange electrical wirings, check lightings		\$	50.00 <i>100</i>
2	To remove, repair & replace damaged bodyparts and where consistent to the accident.		\$	500.00 <i>250</i>
3	Putty and respray painting on affected portions.		\$	500.00 <i>400</i>
4	To remove & refit PDC sensor		\$	80.00 <i>50</i>
5	Rust proofing on affected portions.		\$ <i>Ma</i>	100.00 X
				Labour Total : \$ 1,230.00
				Total Parts & Labour : \$ 4,495.67

*[Signature]*  
 for E M Solution Pte Ltd

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: