



OFFICIAL FERRARI IMPORTER SINGAPORE
Italo Auto Pte Ltd

Date: 8 May 22

EQ INSURANCE
 To: NTUC Income Insurance Co-operative Limited
 Tel:
 Fax:
 email: steve@ntucma.com.sg

QUOTATION
 Our Ref: NA
 Reg. No: 80K4J
 Model: FERRARI F8
 VIN: 200000
 Mileage: NA
 Term: INSURANCE
 Quoted by: C/A



Category	Description	Quantity	Unit Price	Total Price	Handwritten Total
LABOUR	CUT, WELD, REPAIR - FRONT TRELIS, REAR LEFT FENDER (TO BE PLACED ON CAR BENCH FOR REPAIR)	18			44,160 /
	REMOVE AND REPLACE DAMAGED PARTS - FRONT BUMPER & ACCESSORIES, REAR BUMPER & DIFFUSER (REPAIR), LEFT DOOR, LEFT FRONT FENDER, LEFT SIDE SKIRT (REPAIR), QUARTER GLSS, LEFT SIDE MIRROR, LEFT HEADLIGHT, RADIATOR FAN, AIR DUCTS, STEERING BOX, FRONT ARMS AND KNUCKLE, WHEEL HOUSING, 2X WHEEL RIMS, ETC	30	\$ 1,920.00	\$ 57,600.00	
Sub Total Before GST				\$ 59,120.00	
SPRAY PAINTING	RESPRAY PAINT - FRONT BUMPER, REAR BUMPER, LEFT DOOR, LEFT SIDE SKIRT, FRONT LEFT FENDER, REAR LEFT FENDER, LEFT SIDE MIRROR, DIFFUSER, FRONT AND REAR INTERNAL STRUCTURES	1	\$ 18,500.00	\$ 18,500.00	13,200 /
				\$ 18,500.00	
Sub Total Before GST				\$ 18,500.00	
MISCELLANEOUS	DIAGNOSTIC CHECK AND TEST DRIVE, TOP UP AIRCON GAS, REPLACE SOLAR FILM ON QUARTER GLASS, WHEEL ALIGNMENT ETC	8	\$ 240.00	\$ 1,920.00	1680 /
				\$ 1,440.00	
Sub Total Before GST				\$ 1,440.00	
PARTS	REFER TO PARTS LIST	1	\$ 165,047.88	\$ 165,047.88	
				\$ 165,047.88	
Sub Total Before GST				\$ 165,047.88	
Grand Total before Tax:				\$ 252,107.88	
Grand Total including GST:				\$ 269,755.20	

This is an estimate only and does not represent a contract for services. This estimate is based on the scope of the work to be completed for the job as described above. This estimate is based on our evaluation of the requirements necessary to complete the job and does not include material price increases or additional labor and material which may be required should unforeseen problems arise after the work has started. This quotation is valid for thirty (30) days from the date issued.

Steve CLKK)
 26/5/22, 3:32p
 83228813

OP- M M
 Excess - \$25,000
 PIP
 My Bel by
 30 days

Steve CLKK)
 31/6/22, 3:45pm
 Resuming



S/N	TABLE	Ref.	Description	Qty	U/PRICE	E/PRICE
1	63	2	LH WATER RADIATOR / DD	1	3812.16	3812.16
2		14	FAN COWL ? (111)	1	1693.89	1693.89
3	76	1	COMPL. LH FRONT HUB CARRIER ne nec ? (111) - BT	1	4861.18	4861.18
4		7	COMPL. LH FRONT UPPER ARM ? (upper) - BT	1	2508.82	2508.82
5		12	LOWER LH ARM ? / BT	1	3009.14	3009.14
6	83	1	FRONT RIM - CUT	1	2495.15	2495.15
7		1	REAR RIM - CUT	1	2542.74	2542.74
8		4	TYRE PRESSURE MONITORING SYSTE - nec	2	510.6	1021.2
9		5	VALVE. - nec	2	64.05	128.1
10	86	1	STEERING BOX ? / BT	1	10689.46	10689.46
11		12	WASHER ? / nec	2	2.51	5.02
12	98	2	LH FLANK ? X Repair (Front 10)	1	37850.44	37850.44
13		4	FRONT LH FENDER / DD	1	10763.71	10763.71
14		22	ADJUSTMENT SHIM - nec	6	14.42	86.54
15		22	ADJUSTMENT SHIM - nec	2	14.42	28.85
16		23	FORK ADJUSTER SHIM - nec	10	4.79	47.87
17		23	FORK ADJUSTER SHIM - nec	6	4.79	28.72
18		27	RIVET M6X16 - nec	4	3.23	12.93
19		31	RIVET - nec	60	1.7	102
20		32	RIVET - nec	60	1.9	114
21	101	3	COMPL. LH FRONT SUBFRAME / BT	1	1670.02	1670.02
22	104	2	COMPL. LH DOOR STRUCTURE / DD	1	16718.42	16718.42
23		4	SCREW - nec	6	4.57	27.42
24	116	1	RH FRONT WHEELHOUSE / nec	1	1050.39	1050.39
25		2	LH FRONT WHEELHOUSE / TN	1	1050.39	1050.39
26	121	4	FRONT DUCT FOR LH LOWER LATERA - BR	1	67.27	67.27
27	126	1	LH REAR QUARTERLIGHT (q.h.s) - nec X on	1	1173.79	1173.79
28	141	1	COMPL. FRONT BUMPER - BR	1	21536.67	21536.67
29		3	COMPL. LH LATERAL LOWER AERO F - BR	1	4575.36	4575.36
30		6	LH LOWER LATERAL REINFORCEMENT / BT	1	280.8	280.8
31		23	RIVET - nec	30	2.68	80.4
32		27	LH LATERAL MESH - BT	1	170.76	170.76
33	143	1	COMPL. REAR MESH (Rear Bump) - BR	1	25129.43	25129.43
34		84	SCREW - nec	2	1.5	3
35		85	RIVET M6X16 - nec	2	3.23	6.46
36	166	2	LH EXTERNAL REAR VIEW MIRROR - BR	1	1889.68	1889.68
37		4	LH EXTERNAL REAR MIRROR - BR	1	391.81	391.81
38	180	2	HORN, LOW NOTE - BR	1	143	143
39	184	2	LH HEADLAMP - CUT	1	7106.22	7106.22
40		6	LATERAL TURN INDICATOR - CUT	1	174.48	174.48
					S\$	165047.66