

SIN FATT DIESEL MOTOR

8 KAKI BUKIT AVE 4 #05-25 PREMIER @ KB SINGAPORE 415875

TAN TECK HAR
BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

25th MAY 2022

TPEQ
Xiao Chen NZT2603032802

Accident date: 25th MAY 2022

Estimated repair cost for vehicle no: SJN4175K TOYOTA ALLION 1.5A

S/n	Qty	Items	U/price	Amount	
1	1	Rear boot lid <i>Dented</i>			
2	2	Rear boot lid Hinges <i>Bent</i>		\$1,020.00	✓
3	1	Rear boot lid emble logo <i>new</i>	\$105.00	\$210.00	✓
4	1	bootlid allion logo <i>new</i>		\$50.00	✓
5	1	boot lid A15 logo <i>new</i>		\$25.00	✓
6	1	Rear boot lid center moulding <i>crackd.</i>		\$22.00	✓
7	2	Rear boot lid center moulding clips <i>new</i>	\$10.00	\$211.00	✓
8	1	Rear Boot Lid Number Plate <i>new</i>		\$20.00	✓
9	2	Rear Boot Lid Number Plate Lamp <i>new</i>		\$50.00	✓
10	1	Rear boot lid inner lock <i>Dented</i>	\$65.20	\$130.40	✓
11	1	Rear Boot Lid Inner Trim board <i>new</i>		\$285.20	✓
12	10	Rear Boot Lid Inner Trim board clips <i>new</i>	\$10.00	\$495.00	✓
13	1	Rear boot lid inner rubber <i>new</i>		\$100.00	✓
14	2	Rear tail lamp <i>crackd</i>		\$239.10	✓
15	4	Rear tail lamp clips <i>new</i>	\$432.20	\$864.40	750
16	1	Rear Bumper <i>Distorted</i>	\$12.90	\$51.60	20
17	2	Rear Bumper Side Bracket <i>new</i>		\$1,080.00	✓
18	2	Rear bumper side reflector <i>LA crackd</i>	\$125.30	\$250.60	120
19	1	Rear bumper reverse sensor <i>Dented</i>	\$65.00	\$130.00	65
20	8	Rear bumper clips <i>new</i>		\$300.00	20(SN)
21	1	Rear end panel <i>Dented</i>	\$12.90	\$103.20	30
22	1	Rear end panel top garnish <i>Dented</i>		\$488.00	✓
23	1	Rear end Panel Sealant <i>new</i>		\$258.10	✓
24	1	Rear spare tire panel top cover <i>Dented</i>		\$150.00	60(SN)
				\$322.00	250

Labour charges

To Remove & Refix Cushion

To Remove & Refix rear windscreen

Gum

Tuff Kote

To Check Wiring System

To Panel Beating

To Spray Painting

Subtotal :- \$7,560.80

\$100.00 80

\$100.00 X

\$50.00 X

\$120.00 60

\$60.00 30

\$1,100.00 1000

\$1,200.00 1000

Subtotal :- \$2,430.00

Total :- \$9,990.80

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SJN 417511

Supplementary

Tcuillamp Panel LH.

rated

225 ✓

Rees End Panel Antenna Sensor

Rated

195 ✓

Rees Bumper Impact Bracket x 02

LH
Rated

$68 \times 2 = 136$ 68.

488

366.

To remove rear camera.

~~100~~ 50

110

To transfer bootlid fittings.

~~100~~ 60

Supplementary : 476