

FC AUTO GARAGE PTE LTD  
 8 KAKI BUKIT AVE 4  
 #04-03 PREMIER@KB  
 SINGAPORE 415875  
 Mobile: 90110243  
 Co. Reg. No.: 202115045W

Not Authorised  
 Marcus Lee  
 HP90096608



5 days 27/5/22  
 2/5 \$4000

**ESTIMATED REPAIR COST DETAILS**

Take photo After repair

ACC22050007

To: SOMPO INSURANCE SINGAPORE PTE LTD  
 50 RAFFLES PI  
 #03-03 SINGAPORE LAND TOWER  
 SINGAPORE 048623

Date: 26/05/2022  
 Vehicle No.: GBB-3509-X  
 Make: TOYOTA  
 Model: HIACE  
 Chassis No.: JTFHT02P000036010  
 YoM: 2008

Attention: Motor Claim Department

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	REAR TAILGATE <i>3odgros</i>	<i>2091.00</i>	\$2,262.70	—
2	REAR TAILGATE ABSORBER L&R <i>1/1</i>		\$761.00	X
2	REAR TAILGATE HINGE RH & LH <i>1/1</i>		\$178.40	X
1	REAR TAILGATE LOGO <i>1/1</i>	<i>68.50</i>	\$88.60	—
1	REAR TAILGATE WEATHERSTRIP <i>7up</i>	<i>412.60</i>	\$468.00	—
1	REAR TAILGATE INNER TRIM BOARD <i>1/1</i>		\$315.60	X
1	REAR BUMPER <i>D/S</i>	<i>458.80</i>	\$495.80	—
1	REAR BUMPER RETAINER LH <i>one</i>		\$65.80	—
1	REAR BUMPER RETAINER RH <i>1/1</i>		\$65.80	X
4	REAR BUMPER LOWER BRACKET <i>3set</i>	<i>26.40 x 4 = 105.60</i>	\$191.20	?
1	END PANEL INNER <i>R</i>		\$550.00	X
1	END PANEL OUTER <i>DP</i>		\$420.60	?
1	END PANEL TOP GARNISH <i>1/1</i>		\$162.00	X
1	REAR CORNER GARNISH LH <i>2/2</i>		\$98.60	—
1	REAR CORNER GARNISH RH <i>one n/c</i>		\$98.60	X
1	SPARE TYRE BRACKET <i>1/1</i>		\$85.60	X
1	SPARE TYRE CARRIER <i>1/1</i>		\$380.60	X
1	REAR FLOOR PANEL <i>R</i>		\$1,982.50	X
1	PLATE BACK DOOR SCUFF <i>1/1</i>		\$94.50	X
1	TAIL LAMP (LH) <i>one n/c</i>		\$355.60	X
1	TAIL LAMP PANEL LH <i>R</i>		\$596.40	X
1	TAIL LAMP RH <i>one n/c</i>		\$355.60	X
1	TAIL LAMP PANEL RH <i>1/1</i>		\$596.40	X
2	EXHAUST PIPE MOUNTING <i>1/1</i>		\$370.80	X
1	EXHUAST MUFFLER <i>1/1</i>		\$1,565.20	X
1	REAR CORNER PANEL LHS <i>R</i>		\$256.80	X
1	REAR CORNER PANEL RHS <i>1/1</i>		\$256.80	X
<i>1set</i> 1	REAR BUMPER REVERSE SENSOR <i>1/1</i>		\$280.00	<i>200 s/n</i>
1	<i>Tailgate Lock</i> <i>shorted/Dupe</i>		<i>\$350.60</i>	✓

*(252)*

**ESTIMATED REPAIR COST DETAILS**

ACC22050007

<b>Sub Total</b>	<b>\$13,237.50</b>
<b>Discount 25% on Parts</b>	<b>(\$3,309.38)</b>
	<b>\$9,928.13</b>

**Special Nett**

<del>Ref</del> 10	REAR BUMPER CLIPS	all	\$50.00	✓
1	TAILGATE STICKER - 70KM	nee	\$25.00	10
1	REAR WINDSCREEN SEALANT	nee	\$80.00	4.0
Ref 1	PANEL SEALANT	nee	\$95.00	50
1	WINDSCREE AD STICKER - LALAMOVE	nn	\$180.00	X
10	REAR TAILGATE INNER TRIM BOARD CLIPS	nn	\$60.00	X
	<b>Sub Total</b>		<b>\$490.00</b>	

**Labour & Misc**

TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS, INCLUSIVE OF REPLACEMENT PARTS	\$1,200.00	700
TO PUTTY AND RESPRAY PAINTING ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT	\$1,000.00	600
SPRAY RUST PROOF ON AFFECTED AREA	\$80.00	50
TO SUPPLY UNDER COATING/PUTTY ON PARTS REPLACED	\$60.00	X
TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	nn \$60.00	X
DISCONNECT AND CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKET	\$60.00	20
REMOVE AND REFIT REAR WINDSCREEN	\$150.00	120
REMOVE AND REPLACE REVERSE SENSOR	\$60.00	50
DISMANTLE AND TRANSFER TAILGATE FITTINGS AND MECHANISM TO NEW BOOT LID/FACILITATE REPAIR	\$120.00	60
REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	nn \$80.00	X
REMOVE AND REPLACE EXHAUST PIPE/SYSTEM T FACILITATE REPAIR	nn \$100.00	X
<b>Sub Total</b>	<b>\$2,970.00</b>	

<b>Sub Total</b>	<b>\$13,388.13</b>
<b>GST 0%</b>	-
<b>Total</b>	<b>\$13,388.13</b>
	<b>13,772.58</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

P-4072/10  
 252  
 3054.07  
 350  
 1600  
 5004.07  
 202  
 4603.