

ASS. REC. BY:

REF:

C12/22004971/Kt

Kennerth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YM 79437

Yr Regn:

11, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit 1-883

c.c

2977

Colour

white

A/C: Insured / Std / NI / NA

Sp.Reading

341480

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

1-883BCA-10022

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

175 700 R16X10

R:

(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

20/4/22

D.O.I.

30/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear L/H door

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) S + RS. SI

) Fixt

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TPVehicle No. : YM7943TMake & Model : MIT FE83BC6SRDEAYear of Manufacture : 2007Chassis No. : FE83BCA10022Ins Company : CHINA TAIPINGEngine No. : 4M42A42149Excess : Policy No. : Date of Accident : 20/4/22Time of Accident : 0645Suggested Days of Repair : 15In-house Vehicle Assessor**Repair Estimates**Case Owner : BRENDASignature :

Parts (a) Cost / List Price Items \$ -

Plus/Less 15% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less Total of Nett Item

(c) Special Nett Items \$ 1,836.00

Total Parts Cost (Appendix A) \$ 1,836.00

Labour (Appendix B) \$ 2,250.00

Total Repair Cost \$ 4,086.00

Contact No
Frt Counter Operation

Brenda Tel: 63837730 email: brendang@sparkcarcare.com

Back-end Operation

S R Moorthy Tel: 63838115 Em: ramamoorthys@cdge.com.sg

Patrick Tel: 63837466 email: patricktia@sparkcarcare.com

Not Authorized
11 Rm Q

The above total will be subjected to 7% G.S.T.

Name of Surveyor : KennethCompany : LKICSurvey conducted on : 30/5/22 at **Remarks By Surveyor**(a) The repair of this vehicle is not authorized / is not authorized until further notice.(b) Recommended Days of Repair : 03 day(s)(c) Resurvey : Required / Not Required(d) Excess : \$ (e) Signature of surveyor : De Date: 30/5/22

Spark Car Care
ComfortDelGro Engineering Pte Ltd
 205 Braddell Road S (579701)
 Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : YM7943T Case Owner : BRENDA

Make & Model : MIT FE83BC6SRDEA Year Manufacture : 2007

Chassis No : FE83BCA10022 Engine No : 4M42A42149

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LHR DOOR W GASKET	1			<i>CM</i>	\$ 1,700.00	✓
2	STAINLESS STEEL HINGE	1			<i>Di</i>	\$ 136.00	✓
3		1					
4		10					
5		1					
6		1					
7		1					
8		1					
9		10					
10		1					
11		1					
12		1					
13		10					
14		1					
15		1					
16		1					
17		0					
18		0					
19		0					
20		0					
21		0					
22		0					
23		0					
24		0					
25		0					
26		0					
27		0					
28		0					
29		0					
30		0					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Labour

Case Owner : BRENDA
Year of Manufacture : 2007

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 21/04/2022 14:50 (SGT)
Date of Accident 20/04/2022 06:45 (SGT)
Exact Location of Accident 41 Jln Tiga, Singapore 390041
Additional Location Information LOADING AREA
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number YM7943T

INSURED POLICYHOLDER

Is company? Yes
Name Of Registered Owner F&N FOODS PTE LTD
Company Reg No 1XXXXX390K
Email Address yanli.sim@fnnfoods.com
Mobile Phone No (Phone) +65-64612425
Alternative Phone No +65-64612425

VEHICLE PARTICULARS

Manufacturer Mitsubishi
Model FE83BC6SRDEA
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle
Transmission Auto
CC 3000

INSURANCE COMPANY

Name of Insurance Company Allied World Assurance Company, Ltd
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number BVFCSB0013662102
Cover Note Number -

DRIVER

Name of Driver TOH THIAM HOCK
NRIC No SXXXX774Z