

5/30/2022



ComfortDelGro Engineering

205 Braddell Road S(579701)

1st

Our Ref:

### ACCIDENT REPAIR ESTIMATES

Type of Claim : TP

Vehicle No. : YM7943T

Make & Model : MIT FE83BC6SRDEA

Year of Manufacture : 2007

Chassis No. : FE83BCA10022

Engine No. : 4M42A42149

Policy No. :

Time of Accident : 0645

Ins Company : CHINA TAIPING

Excess :

Date of Accident : 20/4/22

Suggested Days of Repair : 15

In-house Vehicle Assessor

Case Owner : BRENDA

Signature :

Contact No  
Frt Counter Operation

Brenda Tel: 63837730 email: brendang@sparkcarcare.com

#### Repair Estimates

Parts (a) Cost / List Price Items \$ -

Plus/Less 15% \$ -

Total of Cost / List \$ -

(b) Nett Price Items \$ -

Less \$ -

Total of Nett Item \$ -

(c) Special Nett Items \$ 1,836.00

Total Parts Cost (Appendix A) \$ 1,836.00

Labour (Appendix B) \$ 2,250.00

Total Repair Cost \$ 4,086.00

#### Back-end Operation

S R Moorthy Tel: 63838115 Em: ramamoorthys@cdge.com.sg

Patrick Tel: 63837466 email: patricktia@sparkcarcare.com

*Not Authorised  
6/ Supp @ 3200h*

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth  
Company : UKIC  
Survey conducted on : 30/5/22 at

#### Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required Not Required

(d) Excess : \$

(e) Signature of surveyor : De Date: 30/5/22



# **Spare Parts**

Vehicle No : YM7943T

Make & Model : MIT FE83BC6SRDEA

Chassis No : FE83BCA10022

Sales Order : \_\_\_\_\_

Order By : \_\_\_\_\_

**Spark Car Care**  
ComfortDelGro Engineering Pte Ltd  
205 Braddell Road S (579701)  
Tel: 63837168 / 63837466 Fax: 62815767

Case Owner : BRENDA

Year Manufacture : 2007

Engine No : 4M42A42149

Supplier : \_\_\_\_\_

Type of Claim : TP

Page 1

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	LHR DOOR W GASKET	1			<i>CM</i>	\$ 1,700.00	✓
2	STAINLESS STEEL HINGE	1			<i>Dis</i>	\$ 136.00	✓
3		1					
4		10					
5		1					
6		1					
7		1					
8		1					
9		10					
10		1					
11		1					
12		1					
13		10					
14		1					
15		1					
16		1					
17		0					
18		0					
19		0					
20		0					
21		0					
22		0					
23		0					
24		0					
25		0					
26		0					
27		0					
28		0					
29		0					
30		0					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

If any of the quoted parts are recommended to be repaired, then an additional labour charge charged accordingly under supplementary.

/30/2022

1:24 PM



ComfortDelGro Engineering Pte Ltd  
205 Braddell Road, Singapore 110015

Tel: 63837168 / 63837466 Fax: 62815767

Vehicle No.

Vehicle No. :

YM7943T

Case Owner

**BRENDA**

Make & Model .

MIT FE83BC6SRDEA

Year of Manufacture

2007

2: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.