

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 9 1993103/9 7825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

TP Budget Direct.
Denise.

GK82103195

24 May 2022

QUOTATION FOR ACCIDENT REPAIR OF SMX9362R HONDA SHUTTLE

THIRD PARTY INSURER: AUTO & GENERAL INSURANCE

S/No.	Parts List	Qty	Amount (\$)
1.	Rear bumper <i>Defect</i>	1	\$ 1152.00 ✓
2.	Rear bumper side retainer L/R <i>RH 2nd</i>	2	\$ 116.00 <i>58</i>
3.	Rear bumper side sponge RH <i>Ren</i>	1	\$ 70.00 <i>+</i>
4.	Rear bumper side reflector RH <i>Ren</i>	1	\$ 62.00 <i>+</i>
5.	Rear taillamp RH <i>Canal</i>	1	\$ 520.80 ✓
6.	Rear fender RH <i>Defect</i>	1	\$ 1334.90 <i>1172</i>
7.	Rear fender inner shield RH <i>Defect</i>	1	\$ 110.00 ✓
8.	Rear fender air vent RH <i>Defect</i>	1	\$ 60.20 ✓
9.	Rear fender inner trim RH <i>Canal</i>	1	\$ 550.00 <i>385</i>
10.	Rear fender glass moulding RH <i>Ren</i>	1	\$ 124.30 ✓
11.	Rear wheel bearing RH <i>2nd</i>	1	\$ 410.60 <i>258</i>
12.	Rear absorber RH <i>Ren</i>	1	\$ 420.80 <i>+</i>
Subtotal before discount			\$ 4931.60
Discount 20%			\$ 986.32
Subtotal 1			\$ 3945.28

S/NETT	Parts List	Qty	Amount (\$)
1.	Rear fender glass sealant RH <i>Ren</i>	1	\$ 80.00 <i>40</i>
2.	Rear fender inner trim board clip RH <i>Ren</i>	1	\$ 30.00 ✓
3.	Rear bumper clip <i>Ren</i>	1	\$ 30.00 ✓
4.	Rear rim RH <i>Ren</i>	1	\$ 280.00 <i>+</i>
5.	Rear rim cover RH <i>cut</i>	1	\$ 200.00 <i>120</i>
6.	Rear tyre RH <i>Ren</i>	1	\$ 350.00 <i>+</i>
S/Nett Total			\$ 970.00

Rear Bumper undercover RH
Defect

\$ 245.00 ✓
95

SIN YU SIN WORKSHOP

Reg No: 53253863C

1 Kaki Bukit Ave 6 #01-52 (Auto Bay @Kaki Bukit) Singapore 417883

Mobile no: (65) 91993103/ 97825292 Fax: (65) 68163103

Email : Sinyusin@hotmail.com

24 May 2022

QUOTATION FOR ACCIDENT REPAIR OF SMX9362R HONDA SHUTTLE

THIRD PARTY INSURER: AUTO & GENERAL INSURANCE

LABOUR

To check wirings.	\$ 80.00 30
To remove and reinstall rear fender glass	\$ 150.00 50
To remove and reinstall rear interior trims, garnish, seats etc	\$ 180.00 60
To remove and replace, refix undercarriage	\$ 350.00 80
To conduct 4 wheel alignment	\$ 120.00 80
To remove and refix rear reverse sensor	\$ 120.00 50
To spray anti-rust coating on new and affected panel	\$ 120.00 60
To straighten, repair, realign on rear affected area and replace damaged parts	\$ 1200.00 700
To spray painting on affected area	\$ 1200.00 500
Total Labour Cost	\$ 3520.00

1610
8,530.28

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ly
H/S 26/05/22

05 days.

Total: 5010.28

H/S: A.K