

ASS. REC. BY: TGum

REF:

CS/CT122004978/Bny3Denise

No mermen

ASSIGNMENT

From: _____ Date: 26/5/2022

Estimated Cost: _____

OD / ~~IP~~ / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SNB 5853Xat Workshop m/s Dean AutoProof 160 Sin Ming Dr #01-14

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 97,000/-

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SNB 5853X Yr Regn: 30/8/2021Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Shuttle c.c. 1496Colour: Purple A/C: Insured / Std / NI / NASp. Reading: 40938 T/Radio: Insured / Std / NI / NAEng/No: L15B6023862C/No: GK8 2103320Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orMod: ☒ S/Rim / STD A/Rim orTyre Size: F: 185/60/15 YokohamaR: 185/60/15 Avanti

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 24/5/2022 D.O.I. 26/5/2022Survey held at Dean AutoProDes. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range : <u>3,000/- - 4,000/-</u>
	Recommended OR : <u>LS \$ 3,200/-</u> (Red, \$ 12,443.84, 80%)
	MV <u>97,000/-</u>
	PV <u>43,478/-</u>
	NV <u>53,522/-</u>

Date/Time, File Pass to?

☐ : Preli. Report1) 12/8/22☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)Rep. Format: TP - mermenLump Sum / L.B. / C: \$3200

SKL 9902 U

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	194N
Vehicle Details	
Vehicle No.:	SNB5853X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	25 May 2022
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE 1.5G CVT SENSING
Primary Colour:	Purple
Manufacturing Year:	2019
Engine No.:	L15B6023862
Chassis No.:	GK82103320
Maximum Power Output:	95.0 kW (127 bhp)
Open Market Value:	\$21,033.00
Original Registration Date:	30 Aug 2021
First Registration Date:	30 Aug 2021
Transfer Count:	0
Actual ARF Paid:	\$6,447.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2031
PARF Rebate Amount:	\$4,835.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2031
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,801.00
COE Rebate Amount:	\$33,440.00
Total Rebate Amount:	\$38,275.00

The information contained herein is correct as at 25 May 2022

OK

MV 97,000/2
PV 43,478/2
NV 53,522/2

TGum Win
26/5/2022

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/05/2022 16:20 (SGT)
Date of Accident	24/05/2022 07:06 (SGT)
Exact Location of Accident	Near 29D Elias Terrace, Singapore 519849
Additional Location Information	ELIAS ROAD TURNING TO ELIAS GREEN
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SNB5853X
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SKYWAY MOTOR PTE LTD
-	199904194N
Email Address	rental@skyway.com.sg
Mobile Phone No	(Phone) +65-63336333
Alternative Phone No	+65-63336333

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Shuttle
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1500

INSURANCE COMPANY

Name of Insurance Company	India International Insurance Pte Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D20MFL0004693_01
Cover Note Number	-

DRIVER

Name of Driver	JEYAKUMAR JASON S/O YASTAIN
NRIC No	S7605917I

Date Of Birth	18/02/1976
Occupation	Indoor
Date Of Driving Pass	31/07/2018
Driving experience	3 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81861030
Alt. Phone Number	-
Email Address	jason@uniforcesecurity.sg
Address	BLK 409SEMBAWANG DRIVE #03-786
Address complement	-
Postcode	750409
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDM833Y
Vehicle Manufacturer	Citroen
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	MIKE
Contact Number	-
Address	-
Address complement	-

Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

Describe Circumstances of the Accident

Waiting at the junction to turn right into the road vehicle behind me bounces into my rear while I was stationary.

Name : Mike
 HP : 9660 3933
 Veh : SOM 8224

Declaration

We declare the foregoing particulars are true in every respect.

Fannie 

Policyholder's Signature / Date & Time

[Signature]

Driver's Signature (if driver is not the policyholder) / Date & Time

24/05/2022

[Signature]

Witnessed by Reporting Centre Personnel *SW CHAI WEN*

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SNB 5853 X**
 Model : Honda Shuttle
 Year : 2021
 Chassis No : GK82103320

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Tailgate	1	\$ 1,458.90	\$ 1254.80 1,458.90	DDV
2	Tailgate logo	1	\$ 78.00	\$ 38.00 78.00	NEC
3	Tailgate outer garnish	1	\$ 471.00	\$ 471.00	NDX
4	Tailgate outer chrome moulding	1	\$ 165.00	\$ 165.00	
5	Tailgate emblem 'Shuttle'	1	\$ 110.00	\$ 52.00 110.00	NEC
6	Tailgate inner lock	1	\$ 258.70	\$ 157.10 258.70	JMV
7	Tailgate weather strip	1	\$ 215.00	\$ 189.00 215.00	TNV
8	Tailgate lamp	2	\$ 782.60	\$ 1,565.20	
9	Tailgate inner trim board	1	\$ 476.80	\$ 476.80	NDX
10	Tailgate inner handler garnish	1	\$ 168.90	\$ 168.90	
11	Tailgate windscreen moulding side	2	\$ 72.00 86.50	\$ 144.00 173.00	NEC
12	Tailgate windscreen moulding top	1	\$ 108.20	\$ 108.20	NSX
13	Tailgate windscreen moulding bottom	1	\$ 108.20	\$ 108.20	NEC
14	Tailgate antenna sensor	1	\$ 228.00	\$ 228.00	NDX
15	Tailgate smart buzzer	1	\$ 195.00	\$ 195.00	
16	Rear bumper	1	\$ 1,150.60	\$ 985.00 1,150.60	BRV
17	Rear bumper side retainer	2	\$ 38.50 105.60	\$ 77.00 211.20	NEC
18	Rear bumper reflector	2	\$ 148.60	\$ 297.20	NDX
19	Rear bumper side sponge	2	\$ 114.20	\$ 228.40	
20	Rear bumper outer chrome moulding	1	\$ 148.60	\$ 148.60	CRAV
21	Rear end panel centre	1	\$ 985.30	\$ 985.30	
22	Rear end panel side	2	\$ 565.60	\$ 1,131.20	NDX
23	Rear end panel top garnish	1	\$ 177.00	\$ 177.00	
24	Taillamp	2	\$ 985.20	\$ 1,970.40	
Parts Sub Total :				\$ 3153.70 12,079.80	
Discount :				\$ 630.74 2,415.96	
PARTS TOTAL :				\$ 9,663.84	

2522.96

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Tailgate sealant	1	\$ 100.00	\$ 30.00 100.00
3	Tailgate outer garnish clips	1	\$ 50.00	\$ 30.00 50.00
4	Tailgate windscreen sealant	1	\$ 100.00	\$ 40.00 100.00
5	Tailgate windscreen inner seal	1	\$ 60.00	\$ 60.00
6	Tailgate windscreen clips	1	\$ 50.00	\$ 50.00
7	Tailgate windscreen primer and cleaner	1	\$ 80.00	\$ 80.00
8	Rear bumper clips	1	\$ 50.00	\$ 30.00 50.00
9	Rear bumper outer chrome moulding clips	1	\$ 50.00	\$ 50.00
10	Rear bumper reverse sensor	2	\$ 250.00	\$ 200.00 500.00
11	Rear end panel sealant	1	\$ 100.00	\$ 100.00
12	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
13	Rear number plate w/casing	1	\$ 80.00	\$ 80.00
SPECIAL NETT TOTAL :				\$ 1,350.00

330.00

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ 80.00 150.00
2	R&R reverse sensor	\$ 60.00 100.00
3	R&R reverse camera	\$ 100.00
4	Check wiring	\$ 100.00
5	Diagnostic reset fault code	\$ 300.00
6	Upholstery	\$ 300.00
7	Conduct water leakage test	\$ 180.00
8	Panel beating	\$ 600.00 1,600.00
9	Rust proofing	\$ 200.00
10	Spray painting	\$ 400.00 1,600.00
LABOUR TOTAL :		\$ 4,630.00

1140.00

PARTS TOTAL : \$ 9,663.84
SPECIAL NETT TOTAL : \$ 1,350.00
LABOUR TOTAL : \$ 4,630.00
GRAND TOTAL : \$ 15,643.84

Survey 26/5/2022
Resurvey 30/5/2022
Tquin kin 1330 hrs
Tquin kin 1445 hrs

Lump sum repair
Repair days 5

LS 3,200/2

Tquin kin
11/6/2022

Parts 2,522.96
SN 330.00
Labour 1,140.00
3992.96
798.59
3194.37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Prepared By Eric (8269-9999) Page 2 of 2
is subject to final approval from Insurance Company

Acknowledged by Repairer