



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFV 1485R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR WINDSCREEN MLDG TOP	NECESSARY	59.50	59.50
1	TAILGATE	BENT	1,072.40	1,072.40
1	TAILGATE EMBLEM	NOT NECESSARY	88.30	-
1	TAILGATE SUBARU LOGO	NECESSARY	72.40	72.40
1	TAILGATE FORESTER LOGO	NECESSARY	72.40	72.40
1	REAR BUMPER	BUCKLED	540.70	540.70
2	REAR BUMPER SIDE RETAINER LH & RH	SERVICEABLE	52.60	-
15	REAR BUMPER CLIPS	NECESSARY	52.50	52.50
1	REAR BUMPER TOW COVER	DENTED	14.30	14.30
1	REAR BUMPER LOWER GARNISH COVER (NPA)	NO SUCH PARTS	-	-
1	REAR BUMPER REINFORCEMENT	BENT	320.90	320.90
1	REAR END PANEL	TO REPAIR SEE LABOUR	320.70	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	30.40	-
	LESS 20% DISCOUNT		-539.42	-441.02
			2,157.68	1,764.08
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REVERSE SENSOR (SN)	SHORTED	200.00	200.00
1	INNER SEAL (SN)	NECESSARY	20.00	20.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
			260.00	260.00
<b><u>LABOUR</u></b>				
	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	15.00
	TO REMOVE AND REINSTALL / REPLACE FRONT / REAR WINDSCREEN.		120.00	120.00
	TO REMOVE AND REINSTALL / REPLACE REAR BUMPER SENSORS.		60.00	50.00
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.		60.00	30.00

Report Ref No. CS/AIS22004982/Kqy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD END PANEL. TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	400.00
	TO SPRAY TAILGATE, REAR BUMPER, END PANEL.		800.00	400.00
			1,880.00	1,015.00
<b>GRAND TOTAL</b>			<b>4,297.68</b>	<b>3,039.08</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,039.08</b>

Report Ref No. CS/AIS22004982/Kqy3e2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.