



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22004982/Kqy3e2	
			Date: 19/10/2022	
			Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLV 966E	Veh. Inspected	SFV 1485R
	Policy No.		Coverage (\$)	0.00
	Claim No.	SEVAISCL2022-0009SL	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	26/05/2022
2. Vehicle Particulars & Condition				
	Make & Model	SUBARU FORESTER (A)	c.c	1995
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JF1SJ5KC5JG111617	Colour	METALLIC SILVER
	Odometer	55952 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/60 R17	YOKOHAMA	7 mm
	L/H Front Tyre	225/60 R17	YOKOHAMA	7 mm
	R/H Rear Tyre	225/60 R17	YOKOHAMA	8 mm
	L/H Rear Tyre	225/60 R17	YOKOHAMA	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/05/2022	Inspection Date	30/05/2022
	Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	