

ASS. REQ. BY:

REF:

A/S/ 220049821K943

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1.B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SFV 1485R

Yr Regn:

09, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Subaru Forester

c.c

1995

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

55952

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JF1SJ3KC5JG111617

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

23/5/22

D.O.I.

30/5/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/10 3039.08 Cabin (Red, 1258.60, 29%)

Date/Time, File Pass to?

☐

: Prel. Report

1) 14/10/22

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

) \$ + RS. SI

) Fuel

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

3039.08

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN BOON TONG
 68 PUNGGOL WALK
 #07-38
 SINGAPORE 828784

Estimate No: MC1902702
 Date: 24 May 2022
 Policy No: MT/00664515/02
 Veh Reg No: SFV1485R
 Make/Model: SUBARU FORESTER
 2.0I-L CVT

ATTN:

Your Ref No: SFV1485R
 Claim Type: Third Party *→ 3rd Party*
 Accident Date: 23/05/2022
 TP Veh Reg No: SLV966E

Not Available
Repair B4 claim
83039.08
4 days

Estimate Repair Cost to Vehicle No :SFV1485R

Description	Quantity	List Price	Amount
		S\$	S\$
SPARE PARTS			
1 REAR WINDSCREEN MLDG TOP	1 PC	<i>M</i> 59.50	<i>✓</i>
2 TAILGATE	1 PC	<i>R</i> 1,072.40	<i>✓</i>
3 TAILGATE EMBLEM	1 PC	<i>nn</i> 88.30	<i>x</i>
4 TAILGATE SUBARU LOGO	1 PC	<i>M</i> 72.40	<i>✓</i>
5 TAILGATE FORESTER LOGO	1 PC	<i>M</i> 72.40	<i>✓</i>
6 REAR BUMPER	1 PC	<i>Buc</i> 540.70	<i>✓</i>
7 REAR BUMPER SIDE RETAINER LH & RH	2 PC	<i>Sm</i> 52.60	<i>x</i>
8 REAR BUMPER CLIPS	15 PC	<i>M</i> 52.50	<i>✓</i>
9 REAR BUMPER TOW COVER	1 PC	<i>na</i> 14.30	<i>✓</i>
10 REAR BUMPER LOWER GARNISH COVER - CHECK PRICE	1 PC	<i>n/a</i> 0.0000	<i>x</i>
11 REAR BUMPER REFLECTOR LH	1 PC	<i>Sm</i> 30.40	<i>x</i>
12 REAR BUMPER REINFORCEMENT	1 PC	<i>R</i> 320.90	<i>✓</i>
13 REAR END PANEL	1 PC	<i>R</i> 320.70	<i>x</i>
		2,697.10	
	Less 20%	539.42	2,157.68
Special Nett			
14 REVERSE SENSOR	1 SET	<i>short</i> 200.00	<i>✓</i>
15 INNER SEAL	1 PC	<i>M</i> 20.00	<i>✓</i>
16 WINDSCREEN SEALANT	1 PC	<i>M</i> 40.00	<i>✓</i>
		260.00	260.00
LABOUR			
17 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>15/</i>
18 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	<i>✓</i>
19 TO REMOVE AND REINSTALL/REPLACE FRONT REAR BUMPER SENSORS.	1 PC	60.00	<i>50/</i>
20 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	<i>30/</i>
21 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD END PANEL.TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	800.00	<i>400/</i>
22 TO SPRAY TAILGATE,REAR BUMPER,END PANEL:	1 PC	800.00	<i>400/</i>
		1,880.00	1,880.00

Zila
 Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN BOON TONG
68 PUNGGOL WALK
#07-38
SINGAPORE 828784

ATTN:

Your Ref No: SFV1485R
Claim Type: Third Party
Accident Date: 23/05/2022
TP Veh Reg No: SLV966E

Estimate No: MC1902702
Date: 24 May 2022
Policy No: MT/00664515/02
Veh Reg No: SFV1485R
Make/Model: SUBARU FORESTER
2.0I-L CVT

Estimate Repair Cost to Vehicle No :SFV1485R

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 4,297.68
		Add GST @ 7%	300.84
		Total Amount Payable	S\$ 4,598.52

TOTAL: SINGAPORE DOLLAR FOUR THOUSAND FIVE HUNDRED NINETY EIGHT AND CENTS FIFTY TWO ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

Zila
Ah Lim Motor Company

AUTHORISED SIGNATURE

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: