



Carway Enterprise

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No. 53096404W

GST Reg. No. M90365035R

☎ 6744 0777

☎ 6744 2377

💻 <http://www.carway.com.sg>

Your Satisfaction is our Success!

Estimate Quotation

Quotation No	May 017/2022
Date	25/5/2022
Vehicle No	SGZ9006E
Make / Model	Mitsubishi Lancer

Yiao Chm.

To: EQ Insurance

JMYSRCY2A 84002746

Qty	DESCRIPTION	UNIT	Amount
	Items		
1 pc	o/s front door <i>Dented</i>		\$ 985.00 ✓
1 pc	outer door moulding <i>Rehd</i>		\$ 165.00 ✓
1 pc	window glass <i>Shattered</i>		\$ 335.00 ✓
1 pc	power window regulator <i>Drnd</i>		\$ 215.00 ✓
1 pc	power window motor <i>new Drnd</i>		\$ 537.00 450.00 380 ✓
1 set	wing mirror assy <i>cracked</i>		\$ 425.00 ✓
1 pc	door handle <i>cracked</i>		\$ 110.00 ✓
1 pc	door handle sensor <i>new</i>		\$ 185.00 ✓
2 pcs	door hinge <i>Best</i>	\$ 68.00	\$ 136.00 ✓
1 pc	lock catch <i>new</i>		\$ 37.00 ✓
1 pc	door lock mechanism <i>Drnd</i>		\$ 279.00 ✓
1 pc	w/strip <i>new</i>		\$ 185.00 ✓
	side-skirt bodykit <i>cracked</i>		\$ 750.00 ✓
	Labour Charge		
	to dismantle damaged parts, panel beat, repair anti rust	1030	\$ 700.00 400 400 ✓
	to putty and spray painting on affected area		\$ 50.00 20 20 ✓
	electrical wiring check		\$ 800.00 500 500 ✓
	remove & replace front door <i>fitting</i>		\$ 50.00 30 30 ✓
			\$ 150.00 80 80 ✓
Subtotal:			\$ 6,094.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Carway Enterprise

Authorised Signature

Adrian L
H/S 26/05/22

04 Days
Total: 4432
H/S: 3.5K ✓