

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : WENG SENG HENG CHINESE MEDICAL HALL
221 HENDERSON RD
#07-15

SINGAPORE 159557

TEL: 62782070

ATTN:

Estimate No: MC1902703

Date: 26 May 2022

Policy No: D21MTPCVE002051

Veh Reg No: GBF2364G

Make/Model: NISSAN NV350 PANEL VAN 2.5

Your Ref No: GBF2364G

Claim Type: Third Party → China

Accident Date: 24/05/2022

TP Veh Reg No: SMX8443Y

*Not written
85080.49
Repair After Paint*

6 days

Estimate Repair Cost to Vehicle No :GBF2364G

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 TAILGATE <i>1986-70</i>	1 PC	2,100.00	✓
2 TAILGATE EMBLEM	1 PC	78.00	✓
3 TAILGATE NV350 LOGO	1 PC	110.00	✓
4 TAILGATE URVAN LOGO	1 PC	64.90	✓
5 TAILGATE LOCK	1 PC	330.00	X
6 TAILGATE INNER TRIM CLIPS	16 PC	88.00	X
7 TAILGATE RUBBER	1 PC	155.00	X
8 TAILAMP RH	1 PC	255.00	✓
9 TAILAMP GROMMET TOP	1 PC	5.50	X
10 TAILAMP GROMMET BTM	1 PC	5.50	X
11 REAR BUMPER	1 PC	667.00	✓
12 REAR BUMPER SIDE RETAINER RH	4 PC	56.00	✓
13 REAR BUMPER CLIPS	7 PC	38.50	✓
14 REAR BUMPER GROMMET	3 PC	16.50	X
15 REAR STEP PANEL	1 PC	210.00	X
16 REAR END PANEL OUTER	1 PC	217.00	X
17 REAR END PANEL INNER	1 PC	576.00	X
18 REAR FENDER OUTER RH	1 PC	2,300.00	X
19 REAR FENDER INNER TRIM CLIPS	17 PC	93.50	X
20 REAR AIR VENT	1 PC	76.00	X
		7,442.40	
	Less 10%	744.24	6,698.16
Special Nett			
21 INNER SEAL	1 PC	20.00	✓
22 WINDSCREEN SEALANT	1 PC	40.00	✓
23 TAILGATE STICKER 8 PAX	1 PC	10.00	✓
24 TAILGATE STICKER 70KM/H	1 PC	10.00	✓
25 TAILGATE STICKER COMPANY NAME - CHECK PRICE	1 PC	NEC 0.00	✓ <i>70</i>
26 TAILGATE STICKER MASCOT - CHECK PRICE	1 PC	0.00	X
27 REVERSE SENSOR	1 SET	200.00	✓
28 REAR FENDER STICKER RH - CHECK PRICE	1 PC	0.00	X
		280.00	280.00
LABOUR			
29 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201

Zila
Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : WENG SENG HENG CHINESE MEDICAL HALL
221 HENDERSON RD
#07-15
SINGAPORE 159557
TEL: 62782070
ATTN:

Estimate No: MC1902703
Date: 26 May 2022
Policy No: D21MTPCVE002051
Veh Reg No: GBF2364G
Make/Model: NISSAN NV350 PANEL VAN 2.5

Your Ref No: GBF2364G
Claim Type: Third Party
Accident Date: 24/05/2022
TP Veh Reg No: SMX8443Y

Estimate Repair Cost to Vehicle No :GBF2364G

Description	Quantity	List Price	Amount
		SS	SS
30 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	120.00	✓
31 TO REMOVE AND REINSTALL/REPLACE FUEL TANK, FIXTURE AND ATTACHMENTS.	1 PC	nn 80.00	X
32 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	60.00	501
33 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	✓
34 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR END PANEL,REAR OUTER FENDER RH. TO KNOCK & REPAIR REAR FLOOR PANEL,REAR INNER FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	1,000.00	7501
35 TO SPRAY TAILGATE,REAR END PANEL,REAR FENDER RH,REAR FLOOR PANEL.	1 PC	1,000.00	8001
		2,360.00	2,360.00
	Total		SS 9,338.16
	Add GST @ 7%		653.67
	Total Amount Payable		SS 9,991.83

TOTAL: SINGAPORE DOLLAR NINE THOUSAND NINE HUNDRED NINETY ONE AND CENTS EIGHTY THREE ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ah Lim Motor Company
AUTHORISED SIGNATURE