

GUAN HIN MOTOR WORKSHOP

NO 10 ANG MO KIO INDUSTRIAL PARK 2A

#02-03 AMK AUTOPOINT 568047

Tel No. : 64837111 Fax No. : 64837221

E-Mail : guanhinmotor@yahoo.com

Buss. Reg. No. : 06035200X PAYNOW

AXA INSURANCE PTE LTD

8 SHENTON WAY

#24-01 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department

Contact : 63387288

Not Authorised
Anthony Bepary

Estimate : ES000957

Date : 31/05/2022

Vehicle Num. : SLW 6974 L

Make/Model : MAZDA 5 WAGEN 2.0 AT EU6-2017

Chassis/Eng# : JM6CW1071H0127630/PE10549476

Accident Date : 24/05/2022

Claim No. :

Reference :

Policy No. : (27/02/2018)

5 days

83933.52

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1	1	LIST ITEMS :		
2	1	FRONT BUMPER	1082.40	
3	1	FRONT BUMPER LH RETAINER		
4	1	LH FOG LAMP GARNISH		
5	1	LH FOG LAMP		
6	1	FRONT LH FENDER	323	
7	1	FRONT LH FENDER INNER SHIELD	211	
8	1	LH HEAD LAMP	1482	
9	1	FRONT SHOCK ABSORBER		
10	1	FRONT LH LOWER ARM		
11	1	FRONT LH KNUCKLE ARM		
12	1	LH SIDE GARNISH		

List Total S\$:

SPECIAL NETT ITEMS :
SPORT RIM

Special Nett Total S\$:

LABOUR :

REMOVE & FIX BACK FRONT BUMPER, FENDER,
HEAD LAMP

REMOVE & FIX BACK UNDERCARRIAGE

WHEEL ALIGNMENT

SPRAY PAINTING

Labour Total S\$:

CM	1,109.00	✓
PR	22.00	✓
PR	79.00	✓
PR	340.00	✓
PR	323.00	✓
CM	217.00	✓
CM	1,482.00	✓
PR	266.00	✓
PR	411.00	✓
PR	386.00	✓
PR	80.00	✓

206

4,715.00

nn 250.00 ✓
250.00

500.00 400

nn 350.00 ✓
120.00 60
800.00 600
1,770.00

Total S\$: 6,735.00



for GUAN HIN MOTOR WORKSHOP

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: