

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Douglas Ong Chu Chong

Date: 13 Jun 2022

Preliminary Advice

Insured	: SLR2141B		
Vehicle No			
TP Vehicle No	: SMY2195Y	Accident Date	: 25/05/2022
Make	: SUBARU FORESTER	Assignment Date	: 26/05/2022
Date of Inspection	: 30/05/2022	Est. Duration of Repair	: 6
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,266.00
Revised Amount	:S\$	7,540.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,540.56

Lump Sum Repair	:S\$	6,000.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	49,000.00
COE / PARF Rebate	:S\$	31,016.00

Salvage Value	:S\$	
Margin for Repair	:S\$	17,984.00

Remarks

- () The vehicle is economical for repair
 - () The vehicle is not economical for repair
 - () Part-by-Part repair
 - (X) Lump Sum repair
-
- (X) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items)
stated are subject to consistency check, part prices and labour cost.