

Arthur Kenneth

Cheng Hoe Motor Pte Ltd

Bik 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

OK
Not authorized
U1 Rny 8/14, 50dp
Returning After Poring
13 days

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 26/05/2022
TP Veh Reg No: SKH6911J

Estimate No: ES2290521/AMK
Date: 27 May 2022
Policy No: DMPCSNW00057612201
Veh Reg No: SJW2148E
Make/Model: BMW BMW 318I 2.0L
Chassis No: WBAPF72040A793605
Engine No: B4861629N46B20BZ
Reg. Date: 10/03/2010

Estimate Repair Cost to Vehicle No :SJW2148E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 FRONT BUMPER	1,064.14	1 PC	1,064.14	✓
2 FRONT BUMPER RH RETAINER	25.10	1 PC	25.10	✓
3 FRONT RH FENDER	670.85	1 PC	670.85	✓
4 FRONT RH FENDER SIGNAL LAMP	60.50	1 PC	60.50	✓
5 FRONT RH FENDER INNER SHIELD (FRT)	124.20	1 PC	124.20	✓
6 FRONT RH FENDER INNER SHIELD (REAR)	124.20	1 PC	124.20	✓
7 WIPER WASHER TANK	130.80	1 PC	130.80	✓
8 RH HEADLAMP	1,022.45	1 PC	1,022.45	✓
9 RH HEADLAMP LOWER BRACKET	95.10	1 PC	95.10	✓
10 FRONT RH DOOR	1,416.20	1 PC	1,416.20	✓
11 FRONT RH DOOR INNER RUBBER	143.40	1 PC	143.40	50% 71.70
12 FRONT RH DOOR TOP HINGE	75.90	1 PC	75.90	✓
13 FRONT RH DOOR BOTTOM HINGE	75.90	1 PC	75.90	✓
14 FRONT RH DOOR CHECKER	100.50	1 PC	100.50	✓
15 FRONT RH DOOR POWER WINDOW MOTOR	328.80	1 PC	328.80	2 X
16 FRONT RH DOOR POWER WINDOW REGULATOR	348.48	1 PC	348.48	✓
17 FRONT RH DOOR WIRE HARNESS	237.45	1 SET	237.45	✓
18 REAR RH DOOR	1,537.20	1 PC	1,537.20	✓
19 REAR RH DOOR INNER RUBBER	143.40	1 PC	143.40	50% 71.70
20 RH SIDE SKIRT	354.35	1 PC	354.35	✓
21 RH SIDE SKIRT CLIPS	30.00	1 SET	30.00	✓
22 REAR RH RIM 16"	755.80	1 PC	755.80	✓
23 FRONT RH RIM 16"	755.80	1 PC	755.80	✓
24 FRONT RH SHOCK ABSORBER	506.60	1 PC	506.60	✓
25 FRONT RH TOP MOUNTING	205.50	1 PC	205.50	✓
26 FRONT RH STOPPER	60.50	1 PC	60.50	✓
27 FRONT RH KNUCKLE ARM	580.50	1 PC	580.50	✓
28 FRONT RH WHEEL BEARING	462.65	1 PC	462.65	✓
29 FRT RH ABS SENSOR WIRE	227.10	1 PC	227.10	✓
30 FRT RH ABS BRACKET	90.20	1 PC	90.20	✓
31 FRT RH BRAKE PIPE BRACKET	50.60	1 PC	50.60	✓
32 FRONT RH STAY LINKAGE	97.10	1 PC	97.10	✓
33 FRONT RH LOWER ARM	234.05	1 PC	234.05	✓
34 FRONT RH TRAILING ARM	234.05	1 PC	234.05	✓
35 STEERING RACK ASSY	2,559.45	1 PC	2,559.45	✓
36 FRONT CROSSMEMBER	1,554.10	1 PC	1,554.10	✓
37 FRONT BUMPER RH FOG LAMP	263.05	1 PC	263.05	✓
38 RH TAILLAMP	421.30	1 PC	421.30	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 26/05/2022
TP Veh Reg No: SKH6911J

Estimate No: ES2290521/AMK
Date: 27 May 2022
Policy No: DMPCSNW00057612201
Veh Reg No: SJW2148E
Make/Model: BMW BMW 318I 2.0L
Chassis No: WBAPF72040A793605
Engine No: B4861629N46B20BZ
Reg. Date: 10/03/2010

Estimate Repair Cost to Vehicle No :SJW2148E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			16109.821716727	
		Less 5%	858.36	16,308.91
			805.49	15304.33
Labour				
39 TOWING	100.00	1 LA	100.00	✓
40 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,FRT RH FENDER,HEADLAMP,BOTH RH DOORS & ATTACHMENTS,RH SIDE SKIRT,TAILLAMP;KNOCKING & REPAIR FRT RH DOOR PILLAR & REALIGN THE SAME	1,200.00	1 LA	1,200.00	1000
41 PUTTY & RESPRAY FRT & REAR BUMPERS,BOTH RH FENDER,BOTH RH DOORS,FRT RH SIDE MIRROR,RH SIDE SKIRT,FRT RH DOOR PILLAR & ALL AFFECTED AREAS	1,300.00	1 LA	1,300.00	1200
42 REMOVE & REFIX FRT RH UNDERCARRIAGE,CROSSMEMBER,STEERING RACK ASSY & REALIGN THE SAME	450.00	1 LA	450.00	320
43 REMOVE & REFIX BOTH RH RIMS,BALANCE & REALIGN THE SAME	80.00	1 LA	80.00	20
44 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	80.00	1 PC	80.00	60
45 RUSTPROOFING	120.00	1 LA	120.00	90
			3,330.00	2790
			3,330.00	3,330.00
			Total	SS 19,638.91
			Add GST @ 7%	1,374.72
			Total Amount Payable	SS 21,013.63

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

Dorlyn LA

AUTHORISED SIGNATURE

15168.09

63-03

2790

43-40

18,164.52

14500

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 26/05/2022
TP Veh Reg No: SKH6911J

Estimate No: ES2290521/AMK
Date: 20 Jun 2022
Policy No: DMPCSNW00057612201
Veh Reg No: SJW2148E
Make/Model: BMW BMW 318I 2.0L
Chassis No: WBAPF72040A793605
Engine No: B4861629N46B20BZ
Reg. Date: 10/03/2010

Estimate Repair Cost to Vehicle No :SJW2148E

Description	U/Price	Quantity	List Price S\$	Amount S\$
Supplementary 1				
1 ENGINE BRACKET LH	CM 66.35	1 PC	66.35	✓
			66.35	
		Less 5%	3.32	63.03
			Total	S\$ 63.03
			GST Amount	S\$ 4.41
			Total Amount Payable	S\$ 67.44

For Cheng Hoe Motor Pte Ltd

Dorlyn LA

AUTHORISED SIGNATURE