

LKK Auto Consultants Pte Ltd

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBF 9625H

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SET STEERING CONE BEARING (N) (CONSISTENT)	NECESSARY	95.00	95.00
1	SET FRONT FORK ASSY (N) (CONSISTENT)	BENT	380.00	380.00
1	FRONT RIM (N) (CONSISTENT)	BENT	180.00	180.00
1	FRONT DISC (N) (CONSISTENT)	NOT NECESSARY	95.00	-
1	SET FRONT DISC SCREW (N) (CONSISTENT)	NOT NECESSARY	30.00	-
1	FRONT WHEEL SHAFT (N) (CONSISTENT)	BENT	48.00	48.00
2	FRONT WHEEL BEARING (N) (CONSISTENT)	NECESSARY	40.00	40.00
1	FRONT METER GEAR UNIT (N) (CONSISTENT)	NOT NECESSARY	55.00	-
1	FRONT BRAKEPAD (N) (CONSISTENT)	NOT NECESSARY	35.00	-
1	CLUTCH LEVER (N) (CONSISTENT)	CUT	28.00	28.00
1	HANDLE BAR (N) (CONSISTENT)	BENT	48.00	48.00
1	HANDLE BAR WEIGHT (N) (CONSISTENT)	BENT	20.00	20.00
1	SET CRASHBAR (N) (CONSISTENT)	BENT	125.00	125.00
1	SET MIRROR (N) (CONSISTENT)	CUT	60.00	60.00
1	SET PILLION L/H FOOTREST (N) (CONSISTENT)	CUT	80.00	45.00
1	SET RIDER L/H FOOTREST (N) (CONSISTENT)	CUT	80.00	45.00
1	BATTERY (N) (CONSISTENT)	NOT NECESSARY	120.00	-
1	GEAR PEDAL (N) (CONSISTENT)	BENT	55.00	55.00
	LESS 10% DISCOUNT		-	-116.90
			1,574.00	1,052.10
	SPECIAL NETT ITEMS			
1	IU UNIT (SN) (CONSISTENT)	BROKEN	200.00	200.00
1	REAR TOP BOX (SN) (CONSISTENT)	CUT	180.00	180.00
			380.00	380.00
	<u>LABOUR</u>			
	LABOUR.		150.00	150.00
	KNOCKING AND RESPRAY FUEL TANK.		180.00	150.00
			330.00	300.00
	GRAND TOTAL		2,284.00	1,732.10

Report Ref No. CS/ASM22005005/Eqcm4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	1,400.00
(TO ITS PRE-ACCIDENT CONDITION)	·

Report Ref No. CS/ASM22005005/Eqcm4



Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser