

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Allianz Insurance Singapore Pte Ltd
79 Robinson Road
#09-01
Singapore 068897

Claim Details
Case Ref. No. : OD/052022/5442
Date : 26-05-2022
Accident Date : 24-05-2022

Vehicle Details

Make & Model : Mercedes Benz C 180
KOMPRESSOR

Chassis No : WDD2040452A679929

Registration No : SKE5461M

S/N	Description	Qty	Amount (\$)
1	LH HEADLAMP / <i>Cut x NV</i>	1.00	\$560.00 ✓
2	LH HEADLAMP TOP PANEL / <i>CCA</i>	1.00	\$180.00 ✗
3	FRONT GRILLE ASSY	1.00	\$480.00 ✓
4	FRONT BUMPER / <i>Dis</i>	1.00	\$880.00 ✓
5	FRONT BUMPER NO. PLATE GARNISH / <i>Re</i>	1.00	\$90.00 ✓
6	FRONT BUMPER CENTRE LOWER GRILLE / <i>Cut</i>	1.00	\$60.00 ✓
7	FRONT BUMPER LH DAYLIGHT	1.00	\$380.00 ✓
8	FRONT BUMPER LH DAYLIGHT COVER	1.00	\$50.00 ✓
9	FRONT BUMPER LH DAYLIGHT COVER CHROME / <i>Dis</i>	1.00	\$50.00 ✓
10	FRONT BUMPER LH CHROME MOULDING	1.00	\$60.00 ✓
11	FRONT BUMPER INNER PAD - LH / <i>BR</i>	1 4.00	\$240.00 60
12	FRONT BUMPER SPONGE / <i>CCA</i>	1.00	\$80.00 ✓
13	FRONT BUMPER REINFORCEMENT	1.00	\$170.00 ✓
14	FRONT BUMPER REINFORCEMENT LH BRACKET / <i>SBT</i>	1.00	\$20.00 ✓
15	FRONT BUMPER UNDER COVER / <i>TN</i>	1.00	\$130.00 ✓
16	FRONT BUMPER CLIP @ \$5.00 / <i>ACC</i>	10.00	\$50.00 ✓
17	FRONT SUPPORT PANEL / <i>BT</i>	1.00	\$50.00 ✓
18	FRONT SUPPORT PANEL TOP COVER / <i>CCA</i>	1.00	\$60.00 ✓
19	AIRCON CONDENSOR / <i>CCA</i>	1.00	\$750.00 ✓
20	AIRCON CONDENSOR RECEIVER PIPE / <i>x NV</i>	1.00	\$260.00 ✗
21	AIRCON CONDENSOR DISCHARGE PIPE / <i>BT</i>	1.00	\$120.00 ✓
22	RADIATOR / <i>Dis</i>	1.00	\$520.00 ✓
23	RADIATOR TOP AIR DUCT / <i>Dis</i>	1.00	\$40.00 ✓
24	RADIATOR LOWER AIR DUCT / <i>Cut</i>	1.00	\$100.00 ✓
25	INTER COOLER / <i>CCA</i>	1.00	\$710.00 ✓
26	WIPER TANK / <i>CCA</i>	1.00	\$110.00 ✓
27	FRONT LH FENDER / <i>CCA</i>	1.00	\$550.00 ✓
28	FRONT LH FENDER INNER SHIELD - FRONT / <i>Dis</i>	1.00	\$70.00 ✓
29	FRONT LH FENDER INNER SHIELD - REAR / <i>x NV</i>	1.00	\$70.00 ✗
30	REONT LH FENDER INNER SHIELD CLIPS @ \$5.00 / <i>CCA</i>	10.00	\$50.00 ✓

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

- 31 FRONT NO. PLATE / BT
- 32 TO REFILL AIRCON GAS
- 33 TO RESET HEADLAMP SYSTEM
- 34 TO REPAIR DAMAGES
- 35 TO SPRAY PAINTING

Margin: 10%

		\$6,940.00	7220
		\$694.00	
		\$7,634.00	7942
1.00	\$40.00	✓	
1.00	\$120.00	✓	
1.00	\$280.00	X NN	
1.00	\$780.00	750	
1.00	\$880.00	700	
		1610	

Subtotal w/o GST:

\$9,734.00

9552

5 Days.
 P/P
 before paint photos.
 Gave Brief
 Not Authorised.
 excess: TBA
 21/5/22.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification to the vehicle
- Supplementary information may be required and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Raymond Teo

This is a computer-generated document. No signature is required.

Front bracket LH ✓ ~~Dis~~ BT ✓ 30

Front LH hallop lower bracket ✓ R's ✓ 180

horn ✓ CRA ✓ 130

Front RH headlamp ✓ CRA ✓ 560

FRONT BUMPER BASE ✓ CRA 70

Tommy
27/5