



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR21005143/Gty3e2-1	
			Date: 09/06/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 5893B	Veh. Inspected	FBR 8944E	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/04/21/2027	Excess (\$)	0.00	
Assign From	ASHLENE LEE	Assign Date	13/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA MX KING T150	c.c	150	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	MH3UG0750LK072816	Colour	BLUE	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	90/80-17	DUNLOP	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	120/70-17	DUNLOP	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/04/2021	Inspection Date	26/04/2021	
Survey held at	EQUATOR BROTHERHOOD 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	