6/16/22, 12:01 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22005016/KVY3M4

16/06/2022 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00115972101

**Claimant Vehicle** 

SLD2768S

Insured

SMN105D

No:

Vehicle No:

Date of Loss:

25/05/2022

Nature of Claim: TP

Claim

Engine No:

Chassis No:

Odometer:

SNM22D203686/02/THAMYL

MMBSTA13AHH000599

3A92UDD7409

115367 km

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SLD2768S** Reg No:

Make & Model: MITSUBISHI ATTRAGE, 1.2 (A)

Reg. Date: 10/06/2016 (Man. Year: 2016)

Metallic Pearl White Colour:

**Engine Capacity:** 1193 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15 Front Left Side: Rear Left Side: Yokohama 8 mm Yokohama 8 mm Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,818.00	1,803.00	15.00	0.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,150.00	820.00	330.00	28.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,968.00	2,623.00	345.00	11.62
Approved Total (Overridden) (S\$)		2,100.00		
(S\$)	2,968.00	2,100.00	868.00	29.25
+ GST 7.00/7.00% (S\$)	207.76	147.00	60.76	29.25
Nett Amount (S\$)	3,175.76	2,247.00	928.76	29.25

**INSPECTION** 

Date of Assignment: 30/05/2022

GLOBAL AUTO SPECIALIST PTE LTD (SING

MING)

Date Inspected: 27/05/2022 Inspected At: 176 SIN MING DRIVE, #04-14 SIN MING

**AUTOCARE** 

SINGAPORE 575721

Estimated Period of Repair: 4.0 days

Adjuster: **KENNETH KONG** Manager: **VERON CHEN** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded

6/16/22, 12:01 PM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Jun 2022)

Parts: 143 MITSUBISHI ATTRAGE 1.2 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLD2768S)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No. Qty Part No.	Part No. Particulars	Condition	Repairer's	Amount
1 1	*FRONT BUMPER	Buckled	666.00 FL	*666.00 FL
2 1	*FRONT BUMPER SIDE RETAINER RH	Distorted	12.00 FL	*12.00 FL
3 1	*FRONT BUMPER GARNISH RH	Scratched	120.00 FL	*120.00 FL
4 1	*FRONT BUMPER TOW HOOK COVER	Dented	59.00 FL	*59.00 FL
5 1	*HEADLAMP RH	Mtg Broken	625.00 FL	*625.00 FL
6 1	*FRONT FENDER RH	Bent	438.00 FL	*438.00 FL
7 1	*FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
8 1	*FRONT NUMBER PLATE W/FRAME	Bent	60.00 FS	*45.00 FS
F=Franchise part. S=SpcNe	art. S=SpcNett. L=ListItemDisc.			
		Sub Total (S\$)	2,010.00	1,995.00
	- List Item Discount on L Items 10.00/10.00% (S\$)		192.00	192.00
		Total Parts (S\$)	1,818.00	1,803.00
		iotal Parts (S\$)	1,818.00	1, ——

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	LABOUR TO REMOVE & REPLACE AFFECTED PARTS AND PANEL BEATING	New	500.00	400.00
2	SPRAY PAINT ON AFFECTED AREAS	New	600.00	400.00
3	TO CONDUCT WIRING CHECK	New	50.00	20.00
	Gross Labou	ır Cost (S\$)	1,150.00	820.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >