

ASS. REC. BY:

REF:

C72 / 220050161kv

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Global Auto Hong Kong

of _____


Insured: **SMN 105D**Policy No. **DMPCSNW00115972101**Claims No. **SNM22D203686/C02/THAMYL**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SID 27885 Yr Regn: 06, 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mit Attrage c.c. 1193Colour: M-P. White A/C: Insured / Std / NI / NASp. Reading: 115367 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NMBSTA 13AHH 000599Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim orTyre Size: F: 185/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

Rear

R/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 25/5/22D.O.I. 27/5/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 EH not ready3/6 L1Rm & 200d

15/6/22 LS \$2100 confirmed by email (red 868, 29%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 15/6/22-typist

Days Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation

S - RS. SI

P. P. P.

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format: Merimen

Lump Sum / L.B. (\$ 2100)

GLOBAL AUTO SPECIALIST PTE LTD

48 TOH GUAN ROAD EAST #06-99 ENTERPRISE HUB SINGAPORE 608586 TEL/FAX: 6464 9291 H/P: 9147 7675
BRANCH: 176 SIN MING DRIVE #05-14 SIN MING AUTOCARE SINGAPORE 575721 TEL/FAX: 6481 7675 H/P: 9639 1626
MAILING ADDRESS: 177 ANG MO KIO AVE 4 #04-911 SINGAPORE 560177
CO / GST REG NO.: 201018026D

ESTIMATE

Mr. Sampah Bin Mahadi

Blk 134 Bukit Batok West Ave 6
Singapore 650134

TEL : 94507604

FAX :

c/o 176 Sin Ming Dr #05-14 Sin Ming Autocare Singapore 575721

*Not with air
11 Rm @ 2000/-
Resurvey After Paint
4 days*

No. : GSQ-2205012

Date : 27-05-2022

Vehicle No. : SLD2768S

Make : MITSUBISHI

Model : Attrage

Accident Date : 25/05/2022

Page : 1 of 1

Item	Description	Qty	U/ Price S\$	Total S\$	
1.	Front bumper <i>666</i>	1.0	<i>Bu</i> 666.00	666.00	✓
2.	Front bumper side retainer RH	1.0	<i>Di</i> 12.00	12.00	✓
3.	Front bumper garnish RH	1.0	120.00	<i>Sen</i> 120.00	✓
4.	Front bumper tow hook cover	1.0	59.00	<i>nd</i> 59.00	✓
5.	Headlamp RH <i>625</i>	1.0	<i>my Bu</i> 625.00	625.00	✓
6.	Front fender RH <i>438</i>	1.0	438.00	<i>Bu</i> 438.00	✓
	Discount 10 %			-192.00	
7.	Front bumper clip	1.0	30.00	<i>na</i> 30.00	✓
8.	Front number plate w/frame	1.0	<i>Bu</i> 60.00	<i>455n</i> 60.00	
9.	Labour to remove & replace affected parts and panel beating	1.0	500.00	500.00	<i>400</i>
10.	Spray paint on affected areas	1.0	600.00	600.00	<i>400</i>
11.	To conduct wiring check	1.0	50.00	50.00	<i>200</i>

SINGAPORE DOLLAR THREE THOUSAND ONE HUNDRED SEVENTY FIVE AND CENTS
SEVENTY SIX ONLY

Sub Total **2,968.00**

Add GST 7% **207.76**

Net Total **3,175.76**

Validity :

Delivery Term :

For and on behalf of

GLOBAL AUTO SPECIALIST PTE LTD



Authorised Signature & Company Stamp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: