



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2302841

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 08/05/2023
Reference CC6/CTI22005019/Upa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SLF 735P
Insured Veh. YN 4179Y
Claim No. SNM22D203706/C02
Policy No. DMCVSNW00075442107
Accident Date 24/05/2022
Inspection Date 27/05/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (8%)	32.00
Grand Total	432.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI22005019/Upa3q2 Date: 08/05/2023 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 4179Y	Veh. Inspected	SLF 735P	
Policy No.	DMCVSNW00075442107	Coverage (\$)	0.00	
Claim No.	SNM22D203706/C02	Excess (\$)	0.00	
Assign From		Assign Date	27/05/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NOTE (A)	c.c	1198	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1TAAE12Z0972339	Colour	GREY	
Odometer	170397 KM	Steering	GOOD	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	ECOPIA	6 mm	
L/H Front Tyre	185/65 R15	ECOPIA	6 mm	
R/H Rear Tyre	185/65 R15	ECOPIA	6 mm	
L/H Rear Tyre	185/65 R15	ECOPIA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/05/2022	Inspection Date	27/05/2022	
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 735P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BADLY DENTED	1,661.90	1,099.10
1	TAILGATE GLASS	SHATTERED	1,198.80	1,198.80
1	TAILGATE WIPER ARM	NOT NECESSARY	89.60	-
1	TAILGATE WIPER ARM COVER	MISSING	18.20	18.20
1	TAILGATE WIPER MOTOR	BENT/ JAMMED	427.00	427.00
1	TAILGATE LOGO	NECESSARY	68.60	68.60
1	TAILGATE EMBLEM 'NOTE'	NECESSARY	72.40	72.40
1	TAILGATE OUTER GARNISH	CRACKED	181.20	181.20
1	TAILGATE OUTER HANDLE	NOT NECESSARY	89.60	-
2	TAILGATE LICENCE LAMPS @\$48.20	NOT NECESSARY	96.40	-
1	TAILGATE INNER LOCK	BENT	183.00	138.50
1	TAILGATE INNER LOCK ACTUATOR	DAMAGED	295.00	295.00
1	TAILGATE INNER TRIM BOARD	DEFORMED /CRACKED	281.60	281.60
1	TAILGATE W/STRIP	TWISTED	162.60	162.60
2	TAILGATE HINGES @\$81.50	NOT NECESSARY	163.00	-
2	TAILGATE DAMPER @\$141.60	NOT NECESSARY	283.20	-
1	TAILGATE INNER PULL POCKET	NOT NECESSARY	86.60	-
2	TAILLAMPS -RH/LH @\$438.00	CRACKED	876.00	876.00
2	TAILLAMPS PANELS -RH/LH @\$225.00	DENTED / BENT	450.00	450.00
1	REAR BUMPER	DISTORTED	667.00	496.80
1	REAR BUMPER SPONGE	TORN	102.60	102.60
2	REAR BUMPER BRACKETS -RH/LH @\$105.00	DENTED	210.00	210.00
2	REAR BUMPER SIDE RETAINERS RH/LH @\$55.00	BENT	110.00	110.00
1	REAR BUMPER LOWER SEAL PLATE	NOT FITTED	68.20	-
1	REAR END PANEL	BADLY DENTED	668.00	597.60
1	REAR END PANEL TRIM	DISTORTED	122.30	74.30
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	486.00	-
2	REAR EXHAUST MOUNTING @\$28.00	NOT NECESSARY	56.00	-
1	REAR EXHAUST INSULATOR	NOT NECESSARY	85.00	-

Report Ref No. CC6/CTI22005019/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FLOOR BOARD	TORN	495.00	468.60
1	REAR FLOOR TOOLS SPONGE	TORN	283.00	283.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	847.00	-
2	REAR FENDERS -LH/RH @\$1155.20	TO REPAIR SEE LABOUR	2,310.40	-
2	REAR FENDER INNER SHIELDS -RH/LH @\$95.50	TORN	191.00	191.00
2	REAR FENDER INNER TRIM BOARDS @\$485.00	DEFORMED / TORN	970.00	970.00
1	REAR FENDER INNER AIR VENT	TWISTED	90.50	90.50
1	REAR SMART KEYLESS ANTENNA	CRACKED	181.20	181.20
1	FRONT BUMPER	DENTED / DEFORMED	552.00	552.00
1	FRONT BUMPER TOW COVER	NOT NECESSARY	42.20	-
1	FRONT BUMPER SPONGE	TORN	218.60	218.60
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	495.00	-
2	FRONT BUMPER SIDE RETAINER -RH/LH @\$45.00	NOT NECESSARY	90.00	-
1	FRONT FENDER -RH	TO REPAIR SEE LABOUR	435.00	-
1	FRONT GRILLE	CRACKED	348.00	348.00
1	FRONT GRILLE LOGO	NOT NECESSARY	68.60	-
1	FRONT GRILLE TOP GARNISH	NOT NECESSARY	286.00	-
2	FRONT HEADLAMPS -RH/LH @\$512.00	O/S CRACKED	1,024.00	512.00
2	FRONT HEADLAMP LOWER BRACKETS @\$65.00	NOT NECESSARY	130.00	-
	LESS 10% DISCOUNT		-1,831.73	-1,067.52
			16,485.57	9,607.68
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	SET FRONT NO.PLATE WITH HOLDER (SN)	BENT	65.00	40.00
1	SET REAR NO.PLATE WITH HOLDER (SN)	BENT	65.00	40.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	30.00
1	REAR REVERSE CAMERA (SN)	SHORTED	450.00	300.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET TAILGATE GLASS SEALANT (SN)	NECESSARY	80.00	40.00
1	SET TAILGATE GLASS FOAM TAPE (SN)	NECESSARY	65.00	30.00

Report Ref No. CC6/CTI22005019/Upa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE GLASS SOLAR FILM (SN)	NECESSARY	280.00	150.00
1	SET REAR FENDER GLASS SEALANT (SN)	NOT NECESSARY	80.00	-
			1,455.00	860.00
	LABOUR			
	TO REMOVE & REFIX REAR TAILGATE GLASS .		300.00	120.00
	TO CHECK FRONT & REAR ELECTRICAL WIRING.		120.00	30.00
	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR .}		150.00	80.00
	TO VACUUM ,WAX & CLEAN REAR INTERIOR TRIMS .}		180.00	-
	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS .		80.00	50.00
	TO REMOVE & REPLACE EXHAUST SYSTEM.	NOT NECESSARY	80.00	-
	TO TUFF KOTE.		150.00	80.00
	TO PUTTY ,SPRAY PAINT & POLISH AFFECTED PARTS.		2,000.00	1,500.00
	TO PANEL BEAT ,CUT ,WELD ,REMOVE & REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST SILENCER,REAR FLOOR PANEL ,REAR FENDERS -RH/LH,FRONT FENDER -RH AND FRONT BUMPER REINFORCEMENT .		3,500.00	1,500.00
			6,560.00	3,360.00
GRAND TOTAL			24,500.57	13,827.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,000.00

Report Ref No. CC6/CTI22005019/Upa3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 735P

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 735P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLF 735P

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

