

FASTECH AUTO PTE LTD  
1 Kaki Bukit Ave 6 #01-48 Autobay  
Singapore 417883  
Tel No: 67452063/ 67467158 Fax No: 67458520  
Tax Reg No : 200006262D

Not Authorized  
RUB  
27/05/22  
1/582900  
3 days.

VEHICLE No: SJY 8317J

1PC	FRONT BUMPER SIDE RETAINER O/S	Scarf	\$89.10	—
1PC	FRONT BUMPER BEAM	R	\$428.10	X
1PC	FRONT BUMPER FOG LAMP O/S	u1	\$385.10	X
1PC	FRONT GRILLE	che n/c	\$781.10	X
1PC	HEADLAMP O/S	one	\$2,850.00	—
1PC	FRONT FENDER O/S	R	\$915.10	X
1PC	FRONT FENDER INNER SHIELD O/S	Torn	\$248.20	—
			\$5,696.70	

1506.50

182.30

(252)

S.NETT

1SET	FRONT BUMPER SPORT TYPE ASSY	Torn	\$2,450.00	1400
1SET	FRONT BUMPER CLIPS	u1	\$50.00	—
1SET	FRONT FENDER INNER SHIELD CLIPS	u1	\$50.00	—
1PC	FRONT SPORT RIM O/S	R	\$850.00	X

TO CHECK WIRING  
TO SPRAY RUST PROOFING  
TO DIAGNOSTIC & RESET SYSTEM  
TO CONDUCT WHEEL ALIGNMENT  
LABOUR FOR PANEL BEATING & REPLACED PARTS  
TO PUTTY & SPRAY PAINTING

	\$50.00	20
u1	\$60.00	X
u1	\$180.00	X
	\$120.00	60
	\$600.00	350
	\$800.00	400
TOTAL	\$10,906.70	

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

1777.9  
252  
1333.42  
1500  
830  
3663.42  
202  
2930.