



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2204976

3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

INV Date 12/08/2022  
Reference CC6/CTI22005027/Upa3q2  
Code CTI

### PROFESSIONAL SERVICE FEE

Vehicle No. SLB 6125G  
Insured Veh. SMW 8835E  
Claim No. SNM22D203591/C02  
Policy No. DMPCSNW00250832101  
Accident Date 21/05/2022  
Inspection Date 27/05/2022

| Description                    | Total         |
|--------------------------------|---------------|
| Third Party Express Settlement | 280.00        |
| <b>Subtotal</b>                | <b>280.00</b> |
| <b>GST (7%)</b>                | <b>19.60</b>  |
| <b>Grand Total</b>             | <b>299.60</b> |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                           |                 |                                                              |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-----------------|--------------------------------------------------------------|--|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909                                         |                                                                                           |                 | Ref: CC6/CTI22005027/Upa3q2<br>Date: 12/08/2022<br>Code: CTI |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                           |                 |                                                              |  |
| Insured Veh.                                                                                                                           | SMW 8835E                                                                                 | Veh. Inspected  | SLB 6125G                                                    |  |
| Policy No.                                                                                                                             | DMPCSNW00250832101                                                                        | Coverage (\$)   | 0.00                                                         |  |
| Claim No.                                                                                                                              | SNM22D203591/C02                                                                          | Excess (\$)     | 0.00                                                         |  |
| Assign From                                                                                                                            |                                                                                           | Assign Date     | 27/05/2022                                                   |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                           |                 |                                                              |  |
| Make & Model                                                                                                                           | TOYOTA COROLLA ALTIS (A)                                                                  | c.c             | 1598                                                         |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                    | Year of Reg.    | 2016                                                         |  |
| Chassis No.                                                                                                                            | MR053REH104547349                                                                         | Colour          | BROWN                                                        |  |
| Odometer                                                                                                                               | 55643 KM                                                                                  | Steering        | AFFECTED                                                     |  |
| Brakes                                                                                                                                 | IN ORDER                                                                                  | Modification    | SPORTS RIM                                                   |  |
| General                                                                                                                                | GOOD                                                                                      |                 |                                                              |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                           |                 |                                                              |  |
|                                                                                                                                        | Size                                                                                      | Make            | Balance                                                      |  |
| R/H Front Tyre                                                                                                                         | 205/55 R16                                                                                | PIRELLI         | 6 mm                                                         |  |
| L/H Front Tyre                                                                                                                         | 205/55 R16                                                                                | PIRELLI         | 6 mm                                                         |  |
| R/H Rear Tyre                                                                                                                          | 205/55 R16                                                                                | PIRELLI         | 6 mm                                                         |  |
| L/H Rear Tyre                                                                                                                          | 205/55 R16                                                                                | PIRELLI         | 6 mm                                                         |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                           |                 |                                                              |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.<br>DAMAGES SEE DETAILS.                                                        |                                                                                           |                 |                                                              |  |
| <b>5. General Information</b>                                                                                                          |                                                                                           |                 |                                                              |  |
| Accident Date                                                                                                                          | 21/05/2022                                                                                | Inspection Date | 27/05/2022                                                   |  |
| Survey held at                                                                                                                         | FASTECH AUTO PTE LTD<br>1 KAKI BUKIT AVENUE 6<br>#01-46/48/50 AUTOBAY<br>SINGAPORE 417883 |                 |                                                              |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                           |                 |                                                              |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                           |                 |                                                              |  |
| <b>5b. Estimate Days of Repair</b>                                                                                                     |                                                                                           |                 |                                                              |  |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                    |                                                                                           |                 | 2 Working Days                                               |  |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 6125G

| Qty | Description of Parts                                                                                   | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>                                                                     |                      |                           |                   |
| 1   | FRONT BUMPER                                                                                           | TO REPAIR SEE LABOUR | 752.10                    | -                 |
| 1   | FRONT BUMPER SIDE RETAINER O/S                                                                         | NOT NECESSARY        | 85.50                     | -                 |
| 1   | SET FRONT BUMPER CLIPS                                                                                 | NECESSARY            | 50.00                     | 50.00             |
| 1   | FRONT FENDER O/S                                                                                       | BENT                 | 715.10                    | 645.10            |
| 1   | FRONT FENDER 'VVTI' EMBLEM O/S                                                                         | NECESSARY            | 105.00                    | 88.50             |
| 1   | FRONT FENDER 'DUAL' EMBLEM O/S                                                                         | NECESSARY            | 80.00                     | 75.00             |
| 1   | FRONT FENDER INNER SHIELD O/S                                                                          | NOT NECESSARY        | 182.10                    | -                 |
| 1   | SET FRONT FENDER INNER SHIELD CLIPS O/S                                                                | NOT NECESSARY        | 50.00                     | -                 |
| 1   | FRONT DOOR O/S                                                                                         | TO REPAIR SEE LABOUR | 1,425.10                  | -                 |
|     | LESS 25% DISCOUNT                                                                                      |                      | -                         | -214.65           |
|     |                                                                                                        |                      | 3,444.90                  | 643.95            |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                                                                       |                      |                           |                   |
| 1   | FRONT SPORT RIM O/S (SN)                                                                               | CUT                  | 2,015.00                  | 600.00            |
|     |                                                                                                        |                      | 2,015.00                  | 600.00            |
|     | <b><u>LABOUR</u></b>                                                                                   |                      |                           |                   |
|     | TO CHECK WIRING.                                                                                       |                      | 50.00                     | 20.00             |
|     | TO SPRAY RUST PROOFING.                                                                                |                      | 60.00                     | 30.00             |
|     | TO DIAGNOSTIC & RESET SYSTEM.                                                                          |                      | 180.00                    | 50.00             |
|     | TO CONDUCT WHEEL ALIGNMENT.                                                                            |                      | 120.00                    | 60.00             |
|     | LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT DOOR O/S . |                      | 600.00                    | 300.00            |
|     | TO PUTTY & SPRAY PAINTING.                                                                             |                      | 800.00                    | 600.00            |
|     |                                                                                                        |                      | 1,810.00                  | 1,060.00          |
|     | <b>GRAND TOTAL</b>                                                                                     |                      | <b>7,269.90</b>           | <b>2,303.95</b>   |

Report Ref No. CC6/CTI22005027/Upa3q2



|                                                                         |  |  |                 |
|-------------------------------------------------------------------------|--|--|-----------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |  |  | <b>1,800.00</b> |
|-------------------------------------------------------------------------|--|--|-----------------|

Report Ref No. CC6/CTI22005027/Upa3q2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SLB 6125G

### INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**PHOTOGRAPHS FOR VEHICLE NO. SLB 6125G**

**RE-INSPECTION**

