

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|---|---|--|----------------|-------|----------------------|
| | CHINA TAIPING IN | ISURANCE (S) PTE LTD | | Ref: | CS3/CTI22005035/Gty3 |
| | 3 ANSON ROAD # SPRINGLEAF TOV | 16-00 VERSINGAPORE 079909 | | Date: | 27/05/2022 |
| | | | | Code: | СТІ |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| | Insured Veh. | XD 9109G | Veh. Inspected | k | SJK 3254M |
| | Policy No. | | Coverage (\$) | | 0.00 |
| | Claim No. | SNM22D203694/C02/XD9109G/ THAMYL | Excess (\$) | | 0.00 |
| | Assign From | JACQUELINE TAN | Assign Date | | 27/05/2022 |
| 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | | c.c | | 0 |
| | Engine No. | HIDDEN | Year of Reg. | | |
| | Chassis No. | | Colour | | |
| | Odometer | - | Steering | | |
| | Brakes | | Modification | | |
| | General | | | | |
| 3. Conditions of Tyres | | | | | |
| | | Size | Make | | Balance |
| | R/H Front Tyre | | | | mm |
| | L/H Front Tyre | | | | mm |
| | R/H Rear Tyre | | | | mm |
| | L/H Rear Tyre | | | | mm |
| 4. | Description of Damages | | | | |
| | | | | | |
| 5. | General Information | | | | |
| | Accident Date | 25/05/2022 | Inspection Dat | e | 27/05/2022 |
| | Survey held at | THIAN CHOON AUTO | | | |
| | | BLK 176 SIN MING DR #05-02 SECTOR C SINGAPORE 575721 | | | |
| 5a. | Remarks | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. | | | | |