

A.S.S. REC-3Y: TauREF: CR/CT/22005036/T 43

ASSIGNMENT

CoE 2025 Jan

From: _____ Date: _____

Estimated cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect/Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 45200

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBH63634 Yr Regn: 2015 Jan

Type: M.Car / M.Bycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Kymco K-XCT200I c.c. 200Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RFB082000 F1 000203Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: N7 / S/Rim / STD A/Rim orTyre Size: F: 120/70R17R: 150/70R13BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 8/6/22

Survey held at

Pang Seow

Des. of Damages: Fr Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

w/s agree CoR is \$3950, 4 days

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2)

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS \$ _____

Photos _____

Others _____

TOTAL

Report Form:

Lum Sum / I.B. / P.

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618

Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: FBH 6363Y

DOA : 21/12/2021

MAKE/MODEL : KYMCO 300

S/No	DESCRIPTION	AMOUNT
1	HANDLER BAR	\$250.00 bjt ✓
2	L/H MIRROR	\$95.00 waf ✓
3	L/H BRAKE LEVER	\$85.00 waf ✓
4	L/H HANDLER END	\$45.00 waf ✓
5	L/H SIDE COWLING	\$398.00 waf ✓
6	L/H SIDE PANEL	\$385.00 lsa ✓
7	L/H LOW PANEL	\$285.00 inf ✓
8	BELT COVER	\$285.00 aut ✓
9	SIDE STAND	\$135.00 X n ✓
10	MAIN STAND	\$295.00 del ✓
11	FORK INNER TUBE X 2	\$750.00 bt ✓
12	FORK OIL SEAL X 2	\$135.00 Re ✓
13	UNDLER BRACKET	\$398.00 bt ✓
14	STEERING CON	\$185.00 per ✓
15	FORK OIL SEAL X 2	\$100.00 Rix n ✓
16	HEAD LIGHT	\$980.00 aut ✓
17	L/H REAR FOOTREST	\$98.00 aut ✓
18	SPRAY COVER SET	\$800.00 HSD
19	TRANSPORT	\$100.00 X n
20	LABOUR	\$600.00 Zoo
	Tanpin 1744574 h wp' 8/6/22 @ 5 pm L/S Kuning after repair tanpin @ kuantan. 4 days	4669 10% 4202.10 750 \$4952.10 L/S \$3950 4 days.
I KK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		Total : \$6,404.00



**SINGAPORE
POLICE FORCE**

Traffic Police
15 Ulu Avenue 3
Singapore 408065
Tel: +65 8547 0000
Fax: +65 8547 6000
www.police.gov.sg

Our Ref : TP/IP/01711/2021
Date : 07 March 2022

ROZAINI BIN SAMSID
APT BLK 327 WOODLANDS STREET 32
#02-07
SINGAPORE 730327

Dear Sir/Madam

**ROAD TRAFFIC ACCIDENT INVOLVING XE3555K AND FBH6363Y ALONG SUNGEI KADUT
AVENUE ON 21.12.2021 AT ABOUT 5.10 P.M**

I refer to the above accident.

2. Please be informed that we have completed our investigations which revealed that the driver/rider of **XE3555K** had committed an offence of **Careless Driving Causing Hurt** under **Section 65(1)(b) of the Road Traffic Act Chapter 276 p/u Section 65(4)(a) of the same Act**. Action has been initiated against the driver/rider for the said offence.
3. If you have any clarification, you may contact the Investigation Officer, Senior Station Inspector Francis Tay Chun Keen at office number: 65476436.
4. Thank you.

Yours faithfully

**HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

This is a computer-generated letter. No signature is required.