

Date: 27/05/2022
 Vehicle No: SNC6856B
 Model: TESLA MODEL 3 STANDARD RANGE
 Chassis: LRW3F7FA2MC384949
 Reg.Year: 2021

*Not withain
 Recovery B&Pain*

Third Party Insurer: CHINA TAIPING
 Third Party Veh No: SLR563E
 Date of Accident: 21/05/2022
 Estimator: KIT
 Surveyor:

3 days

82031.83

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR TAIL LAMP BRACKET RH	1		<i>sm</i> \$2.80
2	REAR BUMPER	1		<i>cm</i> \$663.55
3	REAR BUMPER SIDE BRACKET RH	1		<i>cm</i> \$7.48
4	REAR BUMPER CENTER BRACKET	1		<i>cm</i> \$52.34
5	REAR BUMPER LOWER LIP	1		<i>Di</i> \$140.19
6	REAR BUMPER REFLECTOR RH	1		<i>cm</i> \$20.56
7	REAR BUMPER PARKING SENSOR	<i>shot</i> 2	\$158.88	<i>sm</i> \$317.76
8	REAR BUMPER PARKING SENSOR BRACKET	<i>nu</i> 2	\$4.67	<i>sm</i> \$9.34
9	REAR BUMPER REINFORCEMENT	1		<i>By</i> \$271.03
10	REAR BOOTLID	1		REPAIR
SUB TOTAL				\$1,485.05
LESS 10%				\$148.51
PARTS TOTAL				\$1,336.55

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		<i>nn</i> \$60.00
S/N TOTAL				\$60.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS.

2501
\$500.00

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS.

4401
\$500.00

LABOUR CHARGES TO REMOVE & REPLACE REAR PARKING SENSOR.

601
\$100.00

TO DAIGNOSIS FAULT CODE & RESET MEMORY.

801
\$150.00

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.