

ASS. REC. BY: thuvu

REF:

CS/AGI 22005039 10473

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: 150k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMR 67544 Yr Regn: 17/1/20Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: toyota vofy c.c. 1797Colour: black A/C: Insured / Std / NI / NASp. Reading: 234679 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZWR 800416931Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/65R15R: 195/65R15BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or FarroadFront: 6 mm Rear: 6 mmR/Bal. 6 mm L/Bal. 6 mmD.O.A. 26/5/22 D.O.I. 30/5/22 1600Survey held at NSIDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 150kRebate: 44538MV: 100462

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS SL

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	008R
Vehicle Details	
Vehicle No.:	SMR6754U
Vehicle to be Exported:	No
Intended Deregistration Date:	18 Aug 2022
Vehicle Make:	TOYOTA
Vehicle Model:	VOXY HYBRID 7-SEATER 1.8X CVT
Primary Colour:	Black
Manufacturing Year:	2019
Engine No.:	2ZR2F48877
Chassis No.:	ZWR800416931
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,286.00
Original Registration Date:	17 Jan 2020
First Registration Date:	17 Jan 2020
Transfer Count:	0
Actual ARF Paid:	\$28,601.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2030
PARF Rebate Amount:	\$21,450.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jan 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,900.00
COE Rebate Amount:	\$28,088.00
Total Rebate Amount:	\$49,538.00

The information contained herein is correct as at 18 Aug 2022

OK

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
171 CHIN SWEE ROAD #04-08/09 CES
CENTRE
SINGAPORE 169877

Contact : 87420435, 86990617

TAX INVOICE

Repair Code : CLM17220
Date in : 26/05/2022
Vehicle Num. : SMR6754U
Model : TOYOTA VOXY HYBRID 7-SEATER 1.8X CVT
Chassis/Eng# : ZWR800416931/2ZR2F48877

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER	1	972.25	972.25
REAR BUMPER END SEAL COVER L/R	2	109.30	218.60
REAR BUMPER REFLECTOR L/R	2	59.80	119.60
REAR BUMPER SIDE RETAINER L/R	2	171.70	343.40
REAR BUMPER TOW HOOK COVER	1	42.10	42.10
REAR BUMPER UPPER GARNISH BRACKET L/R	2	185.10	370.20
REAR BUMPER UPPER GARNISH L/R	2	372.80	745.60
REAR CARRIER JACK BRACKET	1	57.30	57.30
REAR END PANEL	1	781.90	781.90
REAR END PANEL ANTENNA SENSOR	1	72.00	72.00
REAR END PANEL INNER TOP GARNISH	1	375.85	375.85
REAR END PANEL SIDE PANEL RUBBER STOPPER	2	43.90	87.80
REAR FENDER INNER TRIM GARNISH L/R	2	781.90	1,563.80
REAR FLOOR PANEL	1	698.70	698.70
REAR FLOOR PANEL JACK BRACKET	1	110.00	110.00
REAR FLOOR PANEL JACK CROSS BRACKET	1	61.60	61.60
REAR FLOOR PANEL TRIM CARPET	1	581.90	581.90
REAR FLOOR PANEL UPPER DECK BOARD COVER	1	1105.50	1,105.50

Heavy Vehicle #01-08 / Spray Painting #02-27
Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
@n51.com.sg
Reg. No. : 200616038C
Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
171 CHIN SWEE ROAD #04-08/09 CES
CENTRE
SINGAPORE 169877

Contact : 87420435, 86990617

TAX INVOICE

Repair Code : CLM17220

Date in : 26/05/2022

Vehicle Num. : SMR6754U

Model : TOYOTA VOXY HYBRID 7-SEATER 1.8X CVT

Chassis/Eng# : ZWR800416931/2ZR2F48877

REAR JACK BRACKET TRIM COVER	1	129.10	BT / 129.10
REAR TAILGATE	1	1815.85	DT / 1,815.85
REAR TAILGATE 'HYBRID SYNERGY DRIVE' EMBLEM	1	50.00	NEC / 50.00
REAR TAILGATE DAMPER L/R	2	371.85	SVC X 743.70
REAR TAILGATE INNER PULL GARNISH	1	33.50	DIS / 33.50
REAR TAILGATE INNER TRIM GARNISH	1	570.30	DT / 570.30
REAR TAILGATE MECHANISM LOCK	1	470 581.90	jam / 581.90
REAR TAILGATE MECHANISM LOCK STRIKER	1	39.00	r x 39.00
REAR TAILGATE OUTER CHROME LOGO	1	69.50	NEC / 69.50
REAR TAILGATE OUTER CHROME MOULDING	1	688 848.00	CUT / 848.00
REAR TAILGATE RUBBER GUIDE STOPPER L/R	2	43.70	SVC X 87.40
REAR TAILGATE SIDE RUBBER STOPPER L/R	2	17.60	SVC X 35.20
REAR TAILGATE WEATHER STRIP	1	374.70	NEC / 374.70
REAR TAILGATE WINDSCREEN MOULDING L/R	2	175.45	NEC / 350.90
REAR TAILLAMP L/R	2	731.35	CLC / 1,462.70

*** This is a computer-generated document which requires no signature.***

Heavy Vehicle #01-08 / Spray Painting #02-27
 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 .51.com.sg
 No. : 200616038C
 ation No. : 200616038C

ATL CAR LEASING PTE LTD
 1 CHIN SWEE ROAD #04-08/09 CES
 CENTRE
 SINGAPORE 169877

Contact : 87420435, 86990617

TAX INVOICE

Repair Code : CLM17220
 Date in : 26/05/2022
 Vehicle Num. : SMR6754U
 Model : TOYOTA VOXY HYBRID 7-SEATER 1.8X CVT
 Chassis/Eng# : ZWR800416931/2ZR2F48877

		Subtotal before discount	15,499.85
Percentage discount	25%		3,874.96
		Sub-total 1	11,624.89
REAR BUMPER CLIPS - SET	1	50.00	50.00
REAR BUMPER REVERSE SENSOR - SET	1	250.00	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	30.00
REAR END PANEL SEALANT	1	100.00	100.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	2	50.00	100.00
REAR FLOOR PANEL SEALANT	1	100.00	100.00
REAR NUMBER PLATE	1	25.00	25.00
REAR NUMBER PLATE HOLDER	1	50.00	50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	80.00	80.00
REAR TAILGATE OUTER CHROME MOULDING CLIPS - SET	1	50.00	50.00
REAR TAILGATE RUBBER MOULDING SEAL	1	80.00	80.00
REAR TAILGATE WINDSCREEN GLASS SEALANT	1	60.00	60.00
		Subtotal before discount	975.00
Percentage discount	0%		0.00
		Sub-total 2	975.00
		Parts-total	12,599.89

*** This is a computer-generated document which requires no signature.***

INITIAL FIE LTD

Heavy Vehicle #01-08 / Spray Painting #02-27
Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
Email: info@initial.com.sg
Reg. No. : 200616038C
Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
171 CHIN SWEE ROAD #04-08/09 CES
CENTRE
SINGAPORE 169877

Contact : 87420435, 86990617

TAX INVOICE

Repair Code : CLM17220
Date in : 26/05/2022
Vehicle Num. : SMR6754U
Model : TOYOTA VOXY HYBRID 7-SEATER 1.8X CVT
Chassis/Eng# : ZWR800416931/2ZR2F48877

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	30	60.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	70	120.00
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	900 800	1,500.00
To remove and reinstall exhaust pipe.	RM X	100.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	900 800	1,700.00
To apply anti-rust chemical on repaired and replaced panel.	40	120.00
To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle.	40	80.00
Labour Total		3,830.00
Parts & Labour Total		16,429.89

*** This is a computer-generated document which requires no signature.***

page 4

F: 9650
RD: 6
Thevan@Lhhauto.com
8235769
L/S 6 days wp
31/5/22 1600
30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: