

ASS. REC. BY:

REF:

GRB/ 22003042/ke

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

1-30pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

856k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1.31

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

23/9 & 17/8-60 Car Ins

Veh No:

SLX 8275

Yr Regn:

04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MIT Attrage

c.c

1193

Colour

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

7887

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MMB STA13A JH 000 741

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

185/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

6

mm

L/Bal.

4

mm

L/Bal.

6

mm

D.O.A.

22/5/22

D.O.I.

3/6/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

OPL

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS, SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / L.B.I. (\$

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimm@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

3/6/22
1:30pm

03/06/22

SURVEYOR COPY

M/S : KOH WEI SHENG VINCENT
BLK 187B RIVERVALE DRIVE #15-862
SINGAPORE 542187

Estimate No: MC1902697
Date: 23 May 2022
Policy No: P10342443R02
Veh Reg No: SLX8275C
Make/Model: MITSUBISHI ATTRAGE
1.2 CVT

ATTN:

Your Ref No: -
Claim Type: Third Party
Accident Date: 22/05/2022
TP Veh Reg No: SLK7170X

Not Notarized
Penalty B&P
\$1718.60 3 days

Estimate Repair Cost to Vehicle No :SLX8275C

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
SPARE PARTS			
1 REAR BOOT EMBLEM	1 PC	41.00	—
2 REAR BOOT LOGO ATTRAGE	1 PC	38.00	—
3 REAR BOOT LOGO MIVEC TECHNOLOGY	1 PC	60.00	—
4 REAR BOOT LOCK	1 PC	206.00	X
5 REAR BOOT LOCK CATCH	1 PC	25.00	1
6 REAR BOOT RUBBER	1 PC	150.00	X
7 REAR BUMPER	1 PC	708.00	—
8 REAR BUMPER SIDE RETAINER LH & RH	2 PC	52.00	X
9 REAR BUMPER CLIPS	12 PC	60.00	—
10 REAR END PANEL	1 PC	402.00	X
11 REAR END PANEL GARNISH	1 PC	65.00	X
		1,807.00	
	Less 20%	361.40	1,445.60
Special Nett			
12 BOOT LOGO CC - check price	1 PC	0.0000	— 28.00
13 NUMBER PLATE (OPC)	1 PC	35.00	—
14 REVERSE SENSOR SET	1 PC	200.00	X
		235.00	235.00
LABOUR			
15 TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	60.00	50
16 TO ARRANGE, SUPPLY AND SEAL OFF PEAK CAR REGISTRATION PLATE INCLUDING INSPECTION FEES BY THE LAND TRANSPORT AUTHORITY.	1 PC	120.00	80
17 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	60.00	X
18 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR END PANEL TO KNOCK & REPAIR SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	700.00	200
19 TO SPRAY BOOT, REAR END PANEL, SPARE TYRE PANEL	1 PC	650.00	400
		1,590.00	1,590.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : KOH WEI SHENG VINCENT
BLK 187B RIVERVALE DRIVE #15-862
SINGAPORE 542187

ATTN:

Estimate No:	MC1902697
Date:	23 May 2022
Policy No:	P10342443R02
Veh Reg No:	SLX8275C
Make/Model:	MITSUBISHI ATTRAGE 1.2 CVT

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 22/05/2022
 TP Veh Reg No: SLK7170X

Estimate Repair Cost to Vehicle No :SLX8275C

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Total		S\$ 3,270.60
	Add GST @ 7%		228.94
	Total Amount Payable		S\$ 3,499.54

TOTAL: SINGAPORE DOLLAR THREE THOUSAND FOUR HUNDRED NINETY NINE AND CENTS FIFTY FOUR ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE