AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg GST:M9-0009639-E RCB NO:06470300B

M/S: INDIA INTERNATIONAL INSURANCE PL

64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711

 Claim No:
 MC1902697

 No:
 AL1907225

 Date:
 29 Sep 2022

Policy No: P10342443R02

Veh Reg No: SLX8275C

ATTN: Make/Model: MITSUBISHI ATTRAGE

1.2 CVT

Your Ref No: - Chassis No: MMBSTA13AJH000741

Claim Type: Third Party TP Ins Co: INDIA

Accident Date: 22/05/2022 TP Veh Reg No: SLK7170X

Tax Invoice-Final Repair Cost to Vehicle No :SLX8275C

	Description	Quantity	List Price <u>S\$</u>	Amount <u>S\$</u>
	SPARE PARTS		**********	
1	REAR BOOT EMBLEM	1 PC	41.00	
2	REAR BOOT LOGO ATTRAGE	1 PC	38.00	
3	REAR BOOT LOGO MIVEC TECHNOLOGY	1 PC	60.00	
4	REAR BUMPER	1 PC	708.00	
5	REAR BUMPER CLIPS	12 PC	60.00	
			907.00	
		Less 20%	181.40	725.60
	Special Nett			
6	BOOT LOGO CC	1 PC	28.00	
7	NUMBER PLATE (OPC)	1 PC	35.00	
8	REVERSE SENSOR SET	1 PC	200.00	
			263.00	263.00
	LABOUR			
9	TO REMOVE AND REINSTALL/REPLACE REAR BUMPER SENSORS.	1 PC	50.00	
10	TO ARRANGE, SUPPLY AND SEAL OFF PEAK CAR REGISTRATION	1 PC	80.00	
	PLATE INCLUDING INSPECTION FEES BY THE LAND TRANSPORT AUTHORITY.			
11	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD REAR END	1 PC	200.00	
	PANEL. TO KNOCK & REPAIR SPARE TYRE PANEL, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.			
12	TO SPRAY BOOT, REAR END PANEL, SPARE TYRE PANEL	1 PC	400.00	
			730.00	730.00
			Total	
		Add GST @ 7%		120.30
		Total Amount Payable		\$\$ 1,838.90

TOTAL: SINGAPORE DOLLAR ONE THOUSAND EIGHT HUNDRED THIRTY EIGHT AND CENTS NINETY ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 03/06/2022

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang. 10 Right Mustrial Pari
#01-09 AMK Autopoint Singapore 5
AUTHORISED SIGNATURE

E. & O. E.