

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/TMI22005043/KQCQ2**Date:** 25/08/2022REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MQ005588

**Claimant Vehicle No :** SHD66U**Insured Vehicle No :** SMD7701P

Date of Loss: 25/05/2022

Nature of Claim: TP Claim No: M2202660

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHD66U**

Make &amp; Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)

Engine No: M9R8839C003033

Reg. Date: 22/03/2016 (Man. Year: 2015)

Chassis No: VF1ABL15AUC282726

Colour: Metallic White/Red

Odometer: 696704 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Sailun 9 mm

Rear Left Side: Sailun 8 mm

Front Right Side: Sailun 9 mm

Rear Right Side: Sailun 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,834.88	3,720.84	2,114.04	36.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	1,035.00	3,325.00	76.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,194.88</b>	<b>4,755.84</b>	<b>5,439.04</b>	<b>53.35</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,800.00</b>		
<b>(S\$)</b>	10,194.88	3,800.00	6,394.88	62.73
<b>+ GST 7.00/7.00% (S\$)</b>	713.64	266.00	447.64	62.73
<b>Nett Amount (S\$)</b>	<b>10,908.52</b>	<b>4,066.00</b>	<b>6,842.52</b>	<b>62.73</b>

INSPECTION

Date of Assignment: 31/05/2022

Date Inspected: 26/05/2022 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)  
2, Ang Mo Kio Street 63  
Singapore 569111

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG    Version: 1.0 (Last Synchronised: 24 Aug 2022)

**Parts:** 143    RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's    (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHD66U)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR PANEL FRT RH	Bent	2,844.66 FL	*2,844.66 FL
2	1		*DOOR HINGE UPPER FRT RH	Repair	274.50 FL	*- FL
3	1		*DOOR HINGE LOWER FRT RH	Repair	300.55 FL	*- FL
4	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
5	1		*FENDER PANEL FRT RH	Bent	437.10 FL	*437.10 FL
6	1		*WHEELARCH FRT RH	Cracked	191.40 FL	*191.40 FL
7	1		*DOOR TRIM CLIP	Not Necessary	70.00 FS	*- FS
8	1		*DOOR MOULDING CLIP	Not Necessary	70.00 FS	*- FS
9	1		*DOOR STICKER TRANSCAB	Necessary	200.00 FS	*60.00 FS
10	1		*DOOR STICKER CLASSIC	Necessary	100.00 FS	*15.00 FS
11	1		*FENDER CLIP	Necessary	70.00 FS	*70.00 FS
12	1		*FENDER LINER CLIP	Not Necessary	65.00 FS	*- FS
13	1		*HUP CAP	Dented	250.00 FS	*250.00 FS
14	1		*FRONT DOOR ADVERTISEMENT STICKER	Necessary	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>6,358.20</b>	<b>4,068.16</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$)</b>	523.32	347.32
<b>Total Parts (\$)</b>	<b>5,834.88</b>	<b>3,720.84</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	230.00	60.00
2	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	440.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	2,000.00	400.00
5	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL	New	220.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,360.00</b>	<b>1,035.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >